



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRTD GSI
Colour	Silver
Year of manufacture	2007
Top speed	110 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	155 BHP
Max. torque	335 Nm at 2.500 rpm
Engine capacity	2.188 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.0 mpg
CO2 emission	218 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-05-26
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2022-06-23
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	71
Total items failed	7

MOT #17	2021-06-24 13:17
---------	------------------

MOT test number	825537797144
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2022-06-23
------------------	------------

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2021-06-21 11:27

**MOT test number**

323624291985

**Result****✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- MAJOR** Front Brake pad(s) contaminated (1.1.13 (b))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- MAJOR** Driver's airbag missing (7.1.5 (a))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15**

2020-06-09 15:31

**MOT test number**

902590198605

**Result**

✓ Passed

**Minor** Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both sides (2.1.3 (g) (i))

**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice** Front Coil spring corroded both sides (5.3.1 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Nearside Front Non obligatory mirror damaged

**Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14**

2018-11-05 16:39

**MOT test number**

303866569327

**Result**

✓ Passed

- Advice** Front Coil spring corroded both (5.3.1 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Under vehicle body has slight corrosion
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Non obligatory mirror damaged
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #13**

2017-05-24 15:10

**MOT test number**

220477881357

**Result**

✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Exhaust corroded
- Advice** Front Tyre worn close to the legal limit both sides (4.1.E.1)
- Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Body has slight corrosion under (6.1.B.2)

**MOT #12** 2017-05-24 15:10**MOT test number** 310432755077**Result** ✗ Failed

- Advice** Front Tyre worn close to the legal limit both sides (4.1.E.1)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Body has slight corrosion under (6.1.B.2)
- Advice** Exhaust corroded
- Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #11** 2016-05-03 09:35**MOT test number** 515426991545**Result** ✓ Passed

- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Offside Front Tyre worn close to the legal limit inner edges (4.1.E.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #10** 2015-04-29 09:08**MOT test number** 955409115199**Result** ✓ Passed

- Notice** Slight power steering leak around rack
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9** 2015-04-23 08:12**MOT test number** 748503115141**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Slight power steering leak around rack
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #8** 2014-04-30 16:33**MOT test number** 507740424124**Result** ✓ Passed

- Notice** Front wipers smearing
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #7** 2014-04-29 12:17**MOT test number** 985779914182**Result** ✗ Failed

- Fail** Offside Rear fog lamp insecure (1.3.2a)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Notice** Front wipers smearing
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #6** 2013-06-04 16:23**MOT test number** 478875753103**Result** ✓ Passed**MOT #5** 2013-05-25 11:50**MOT test number** 607205043113**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2012-09-05 17:49**MOT test number** 418519342205**Result** ✓ Passed**MOT #3** 2011-06-07 13:59**MOT test number** 437018851162**Result** ✓ Passed**MOT #2** 2011-06-06 14:35**MOT test number** 949387051109**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2010-06-17 10:53**MOT test number** 891858860133**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 December 2021

✕  
MOT

Expired:  
23 June 2022

Tax status	Expired at 31 December 2021
Days left	850 days too late
MOT expiry date	23 June 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>EN07SVD</b>
Plate since	2019-09-28
Current registration	<b>EN07SVD</b>
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-06-26
Last registration	2021-06-24
Complete history	<a href="#">See info</a>



Registration #1	2007-06-26	20 mi
Registration #2	2010-06-17	14.027 mi
Registration #3	2011-06-06	20.206 mi
Registration #4	2011-06-07	20.207 mi
Registration #5	2012-09-05	25.098 mi
Registration #6	2013-05-25	31.885 mi
Registration #7	2013-06-04	31.885 mi
Registration #8	2014-04-29	41.446 mi
Registration #9	2014-04-30	41.472 mi
Registration #10	2015-04-23	51.571 mi
Registration #11	2016-06-20	55.377 mi
Registration #12	2016-06-20	55.377 mi
Registration #13	2016-06-20	55.377 mi
Registration #14	2016-06-20	55.377 mi
Registration #15	2016-06-20	55.377 mi
Registration #16	2016-06-20	55.377 mi
Registration #17	2016-06-20	55.377 mi
Registration #18	2016-06-20	55.377 mi
Registration #19	2016-06-20	55.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1725 mm
Length	4650 mm
Wheel base	2700 mm
Kerb weight	1893 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	D4EB7267182