





report date: 2024-03-28

General information

Make	KIA
Model	SOUL CRDI SHAKER
Colour	Cream
Year of manufacture	2009
Top speed	113 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	45.6 mpg
CO2 emission	137 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 3

Date 2022-11-11

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2


Date	2022-05-08
------	------------

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-09-05

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-04
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	14
Total items failed	7

MOT #16	2023-08-01 14:13
MOT test number	619290135136
Result	✓ Passed
Next expiry date	2024-08-04

MOT #15	2023-07-27 13:04
MOT test number	732666186447
Result	X Failed
Fail Offside Headlamp aim too low (4.1.2 (a))	
Fail Offside Front Inner Tyre has a tear, caused by separation or partial failure of its (ii))	structure (5.2.3 (d)
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Headlamp aim too low (4.1.2 (a))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #14	2022-07-26 10:58
MOT test number	438639249318
Result	✓ Passed
MOT #13	2021-07-28 10:12
MOT test number	233135068476
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12		2020-07-06 15:18
MOT test	number	421335262493
Result		✓ Passed
MOT #11		2019-08-05 15:30
MOT test	number	297484103273
Result		✓ Passed
MOT #10		2018-07-03 10:56
MOT test	number	806497160029
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2018-06-30 11:52
MOT test number	459349939708
Result	X Failed
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2017-07-04 14:56
MOT test number	856070945170
Result	Passed

MOT #7	2017-07-04 11:54
MOT test number	413746796065
Result	× Failed
Fail Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.10	c)

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #6 2016-06-29 12:32

MOT test number 401718050558

MOT #5 2015-06-11 11:47

MOT test number 599152165115

Result \rightarrow Passed

Advice Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Notice Cut in offside front tyre

Advice Offside Inner Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4 2014-06-19 16:37

MOT test number 209160374172

Result ✓ Passed

MOT #3 2014-06-19 10:55

MOT test number 238320874151

Result X Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Notice Ns wiper split

MOT #2 2013-06-28 14:26

MOT test number 309539973181

Result
✓ Passed

Notice Slight damage to nearside front tyre sidewall

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	4 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

LS09LMX

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this KIA had different number plates.

WK UK

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-06-30
Last registration	2023-08-01
Complete history	See info



Registration #1	2009-06-30	12 mi
Registration #2	2012-06-22	17.737 mi
Registration #3	2013-06-28	23.777 mi
Registration #4	2014-06-19	30.041 mi
Registration #5	2014-06-19	30.041 mi
Registration #6	2015-06-11	35.686 mi
Registration #7	2016-06-29	43.467 mi
Registration #8	2017-07-04	51.901 mi
Registration #9	2017-07-04	51.901 mi
Registration #10	2018-06-30	58.965 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.117 au

More info >

CarCheck.co.uk page 12/13



LS09LMX report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1345 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2

Engine number D4FB8H507496