





General information

| Make | PEUGEOT |
|---------------------|----------------|
| Model | 206 LOOK HDI |
| Colour | Silver |
| Year of manufacture | 2007 |
| Top speed | 104 mph |
| 0 - 60 mph | 14.8 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 67 BHP |
|-------------------------|---------------------|
| Max. torque | 160 Nm at 1.750 rpm |
| Engine capacity | 1.398 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 76.4 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 112 g/km |
| CO2 label | С |





MOT history

| MOT expiry date | 2021-10-15 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 12 |
| Failed MOT tests | 3 |
| Total advice items | 21 |
| Total items failed | 4 |

| MOT #15 | 2020-10-07 15:04 | |
|--|------------------|--|
| MOT test number | 445485330747 | |
| Result | ✓ Passed | |
| Next expiry date 2021-10-15 | | |
| Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) | | |
| Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) | | |

| MOT #14 | 2019-10-15 13:17 |
|--|------------------|
| MOT test number | 484757358209 |
| Result | ✓ Passed |
| Advice Windscreen scratched | |
| Advice Items removed from driver's view prior to test | |
| Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) | |
| Advice O/s door check strap noisy | |



| KU07XEV |
|-------------------------|
| report date: 2024-03-29 |

| MOT #13 | | 2018-10-15 13:43 |
|----------|--|------------------|
| MOT test | number | 186627443818 |
| Result | | ✓ Passed |
| Advice | O/s/f tyre 3mm | |
| Advice | N/s/f tyre 2mm | |
| Advice | Both rear tyres perished | |
| Advice | Items removed from driver's view prior to test | |
| | | |
| MOT #12 | | 2017-10-16 14:50 |
| MOT test | number | 633651464763 |
| Result | | ✓ Passed |

Advice Both rear tyres perished and cracked

Advice O/s/f track rod end slight play

| MOT #11 | | 2016-10-11 15:53 |
|----------|-------------------------------------|------------------|
| MOT test | number | 736105425148 |
| Result | | ✓ Passed |
| Advice | O/s/f tyre getting low and perished | |
| Advice | N/s/f tyre getting low and perished | |
| Advice | N/s/r tyre perished | |





| MOT #10 | 2016-10-11 12:50 |
|---|------------------|
| MOT test number | 491098680522 |
| Result | 🗙 Failed |
| Advice N/s/f tyre getting low and perished | |
| Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3) | |
| Advice N/s/r tyre perished | |
| Advice O/s/f tyre getting low and perished | |
| MOT #9 | 2015-10-14 10:44 |
| MOT test number | 424350969927 |
| Result | ✓ Passed |

| MOT #8 | 2015-03-02 13:24 |
|-----------------|------------------|
| MOT test number | 476991065009 |
| Result | ✓ Passed |

| MOT #7 | | 2015-03-02 13:24 |
|-------------------------|--|------------------|
| MOT test number | | 439141965073 |
| Result | | 🗙 Failed |
| Pass with rectification | Offside Headlamp aim too far to the left (1.8) | |
| Pass with rectification | Nearside Headlamp aim too far to the right (1.8) | |

| MOT #6 | | 2014-02-27 11:29 |
|----------|---|------------------|
| MOT test | number | 129728154425 |
| Result | | ✓ Passed |
| Notice | Exhaust system part slightly deteriorated | |
| Notice | Front wiper blades worn | |





| MOT #5 | | 2013-02-25 09:46 |
|-------------------------|--------------------------------------|------------------|
| MOT test number | | 777226253034 |
| Result | | ✓ Passed |
| | | |
| MOT #4 | | 2012-02-14 11:16 |
| MOT test number | | 546905742020 |
| Result | | ✓ Passed |
| | | |
| МОТ #3 | | 2012-02-14 11:16 |
| MOT test number | | 177995242422 |
| Result | | 🗙 Failed |
| Pass with rectification | Nearside Headlamp aim too high (1.8) | |

| MOT #2 | 2011-02-14 09:51 |
|--|------------------|
| MOT test number | 618755741088 |
| Result | ✓ Passed |
| Notice Nearside front tyre worn on the outer edge | |

| MOT #1 | 2010-02-16 12:51 |
|-----------------|------------------|
| MOT test number | 203957240040 |
| Result | ✓ Passed |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---|
| Date | |
| Category | 4. DEM PE |
| Туре | |
| Damage 2 | Annet |
| Date | No. Contraction of the second |
| Category | AMP |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2007-03-07 |
| Last registration | 2020-10-07 |
| Complete history | See info |



| Registration #1 | 2007-03-07 | 22 mi |
|---|------------|---|
| Registration #2 | 2010-02-16 | 11.973 mi |
| Registration #3 | 2011-02-14 | 17.264 mi |
| Registration #4 | 2012-02-14 | 21.965 mi |
| Registration #5 | 2013-02-25 | 24.867 mi |
| Registration #6 | 2014-02-27 | 27.007 mi |
| Registration #7 | 2015-03-02 | 29.084 mi |
| Destates #0 | | |
| Registration #8 | | |
| Registration #8 | | 11.777 mi |
| | | 10.202 est |
| Registration #9 | | 10.202 est 10.202 est 10.202 est |
| Registration #9 Registration #10 | | 0.000 est 0.000 est 0.000 est 0.000 est |
| Registration #9 Registration #10 Registration #11 | | 0.202 est 0.202 est 0.202 est 0.202 est 0.202 est |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| S0501 | |
| 50566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1652 mm |
| Height | 1433 mm |
| Length | 3822 mm |
| Wheel base | 2445 mm |
| Kerb weight | 1049 kg |
| Max. allowed weight | 1525 kg |
| Additional information | |
| Fuel tank capacity | 50 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | FD951827264 |