





report date: 2024-03-28

### General information

Make	FIAT
Model	DOBLO MYLIFE
Colour	Blue
Year of manufacture	2014
Top speed	100 mph
0 - 60 mph	15.4 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	95 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/11



## Internet history

### Entry 2

Date	2021-05-26	
------	------------	--

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

#### Entry 1

Date	2021-01-29	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-01
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	14
Total items failed	4

MOT #9	2023-10-18 10:04
MOT test number	108190408724
Result	✓ Passed
Next expiry date	2024-11-01
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2022-11-01 14:33
MOT test number	736023451807
Result	✓ Passed
Advice Rear Passenger seat(s) missing at time of test Central and offside seats motibility vehicle	s removed converted to
Advice Rear Rear bump stop mountings corroded.	
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge 195/60 F	R16C (Urgent. (5.2.3 (e))

MOT #7	2021-11-02 13:33
MOT test number	836643756099
Result	<b>✓</b> Passed
MOT #6	2019-05-14 15:41
MOT test number	886804193599
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



MOT test number

Result

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Service brake efficiency less than 50% of the required value (1.2.2 (a) (ii))

MOT test number

Result

Advice Offside Front tyre bold inner and outer edge

Advice Nearside Front tyre bold on inner and outer edge

Advice Nearside Rear tyre bold inner edge

MOT test number

354748679555

Result

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Rear tyre bold inner edge

Advice Offside Front tyre bold inner and outer edge

Nearside Front tyre bold on inner and outer edge

MOT #2

MOT test number

782363739464

Result

Advice Nearside Rear tyre bold inner edge

Advice Offside Rear tyre bold inner edge

CarCheck.co.uk page 4/11



MOT test number

Result

Advice Nearside Rear tyre bold inner edge

Fail Nearside Body has a sharp edge caused by damage wing mirror (6.1.C.1)

Advice Offside Rear tyre bold inner edge

CarCheck.co.uk page 5/11



# Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	1 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/11



### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/11



$\sim$		
Owner	hictory	7
OWITCE	1113601	1

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-05-30
Last registration	2023-10-18
Complete history	See info



Registration #1	2014-05-30	11 mi
Registration #2	2017-05-02	15.090 mi
Registration #3	2017-05-03	15.091 mi
Registration #4	2018-05-24	20.956 mi
Registration #5	2018-05-24	20.960 mi
Registration #6	2019-05-14	22.719 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		n

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Wheel base	2755 mm
Kerb weight	1340 kg
Max. allowed weight	1975 kg

# Additional information

Fuel tank capacity	60 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	page 1	1/11

Number of axles 2

Engine number 4035743