



F J18

report date: 2024-03-28

General information

Make	VOLVO
Model	V50 T5 R-DESIGN
Colour	Blue
Year of manufacture	2009
Top speed	149 mph
0 - 60 mph	6.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.0 mpg
Consumption extra urban	42.2 mpg
Consumption combined	30.1 mpg
CO2 emission	203 g/km
CO2 label	K





Internet history

Entry 1	
Date	2021-11-17
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-05-04
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	29
Total items failed	1

MOT #15	2023-04-28 06:54
MOT test number	940876511881
Result	✓ Passed
Next expiry date	2024-05-04
Advice	Exhaust has a minor leak of exhaust gases corroded around weld, main pipe into rear box (6.1.2 (a))

MOT #14	2022-04-27 09:49
MOT test number	631156915937
Result	✓ Passed

MOT #13	2022-04-25 11:33
MOT test number	369720373769
Result	✗ Failed
MAJOR	Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #12	2021-05-05 15:25
MOT test number	293818445178
Result	✓ Passed
Advice	Rear surface corrosion
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2020-07-22 09:19

MOT test number

368134382927

Result

✓ Passed

- Advice** Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Rear Upper Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2019-04-24 09:08

MOT test number

386188744546

Result

✓ Passed

MOT #9

2019-04-23 09:36

MOT test number

721483304741

Result

✗ Failed

- DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #8

2018-04-27 09:29

MOT test number

938105295439

Result

✓ Passed

**MOT #7** 2017-05-02 08:19**MOT test number** 973209550619**Result** ✓ Passed**MOT #6** 2016-09-22 08:47**MOT test number** 986488376500**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #5** 2015-09-11 10:53**MOT test number** 232695440812**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front brake disc modified but not seriously weakened (3.5.1n)**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #4** 2014-09-16 12:05**MOT test number** 309239154273**Result** ✓ Passed**Advice** Offside Front Power steering component(s) has slight seepage from a component (2.3.3b)**Advice** Offside Rear Road wheel slightly damaged (4.2.A.1a)**Advice** Nearside Rear Road wheel slightly damaged (4.2.A.1a)

**MOT #3** 2014-09-16 12:05**MOT test number** 397359854238**Result** ✗ Failed**Advice** Offside Front Power steering component(s) has slight seepage from a component (2.3.3b)**Advice** Offside Rear Road wheel slightly damaged (4.2.A.1a)**Pass with rectification** Offside Front Steering rack gaiter insecure (2.2.D.2d)**Advice** Nearside Rear Road wheel slightly damaged (4.2.A.1a)**MOT #2** 2013-09-24 12:31**MOT test number** 469227563244**Result** ✓ Passed**MOT #1** 2012-09-26 15:22**MOT test number** 938900972290**Result** ✓ Passed**Notice** Front tyres inner shoulder wearing low**Notice** Offside rear tyre worn low, 3mm



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
4 May 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	4 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-26
Last registration	2023-04-28
Complete history	See info



Registration #1	2009-09-26	26 mi
Registration #2	2012-09-26	26.258 mi
Registration #3	2013-09-24	35.616 mi
Registration #4	2014-09-16	44.846 mi
Registration #5	2015-09-11	50.707 mi
Registration #6	2016-09-22	61.406 mi
Registration #7	2017-05-02	65.773 mi
Registration #8	2018-04-27	74.469 mi
Registration #9	2019-05-20	85.277 mi
Registration #10	2020-05-20	95.277 mi
Registration #11	2021-05-20	105.277 mi
Registration #12	2022-05-20	115.277 mi
Registration #13	2023-05-20	125.277 mi
Registration #14	2024-05-20	135.277 mi
Registration #15	2025-05-20	145.277 mi
Registration #16	2026-05-20	155.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1444 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number	4420034
---------------	---------