



PEUGEOT



SFI3FYG

report date: 2024-03-28

General information

Make	PEUGEOT
Model	HORIZON E-HDI TEPEE S
Colour	Silver
Year of manufacture	2013
Top speed	103 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	58.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-01
Pictures	38
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-19
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	38
Total items failed	2

MOT #16	2024-04-17 08:43
MOT test number	834503144062
Result	✓ Passed
Next expiry date	2025-04-19
Advice	Coolant low
Advice	Rear seat folded down not allowing inspection of seat belts
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

MOT #15	2024-04-17 08:43
MOT test number	463347408737
Result	✗ Failed
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
Advice	Rear seat folded down not allowing inspection of seat belts
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Coolant low

**MOT #14**

2023-04-11 14:03

**MOT test number**

489032617396

**Result**

✓ Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Standard fitment seat belt missing**MOT #13**

2022-04-14 16:39

**MOT test number**

945726701128

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Standard fitment seat belt missing**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Nail in tyre**MOT #12**

2022-04-14 16:39

**MOT test number**

374259074087

**Result**

✗ Failed

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Standard fitment seat belt missing**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Nail in tyre

**MOT #11**

2022-02-02 10:36

**MOT test number**

366043996330

**Result****✗ Failed****DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Windscreen damaged and affecting the driver's view of the road chip over 10mm zone A (3.2 (a) (ii))**MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Brake performance not tested due to condition of pads (1.2.1 (g))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Rear Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #10**

2021-04-20 12:53

**MOT test number**

885564280693

**Result****✓ Passed****MOT #9**

2021-04-14 09:09

**MOT test number**

715964710888

**Result****✗ Failed****MAJOR** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #8**

2020-07-08 13:18

**MOT test number**

772807706826

**Result****✓ Passed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #7</b>	2019-08-16 10:21
<b>MOT test number</b>	271110374776
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #6</b>	2019-08-14 09:26
<b>MOT test number</b>	989939784655
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>DANGEROUS</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>MAJOR</b>	Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>MAJOR</b>	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

<b>MOT #5</b>	2018-10-04 11:13
<b>MOT test number</b>	720841615820
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2018-10-03 11:51
<b>MOT test number</b>	948560915153
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>MAJOR</b>	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
<b>MAJOR</b>	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>MAJOR</b>	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))



MOT #3	2017-10-30 12:25
MOT test number	974561941361
Result	✓ Passed
MOT #2	2016-12-07 13:42
MOT test number	599533692401
Result	✓ Passed
MOT #1	2016-02-10 11:42
MOT test number	521839485939
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
19 April 2025

<b>Tax status</b>	Valid until 1 July
-------------------	--------------------

<b>Days left</b>	64
------------------	----

<b>MOT expiry date</b>	19 April 2025
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-04-06
Last registration	2024-04-17
Complete history	<a href="#">See info</a>



Registration #1	2013-04-06	24 mi
Registration #2	2016-02-10	26.298 mi
Registration #3	2016-12-07	33.881 mi
Registration #4	2017-10-30	42.416 mi
Registration #5	2018-10-03	48.650 mi
Registration #6	2018-10-04	48.650 mi
Registration #7	2019-08-14	55.983 mi
Registration #8	2019-08-16	55.983 mi
Registration #9	2020-07-08	62.037 mi
Registration #10	2020-07-08	62.037 mi
Registration #11	2020-07-08	62.037 mi
Registration #12	2020-07-08	62.037 mi
Registration #13	2020-07-08	62.037 mi
Registration #14	2020-07-08	62.037 mi
Registration #15	2020-07-08	62.037 mi
Registration #16	2020-07-08	62.037 mi
Registration #17	2020-07-08	62.037 mi
Registration #18	2020-07-08	62.037 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1624 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	JBFR3002211