



General information

Make	VOLVO
Model	S40 R-DESIGN EDITION
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	37.2 mpg
CO2 emission	176 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-10-14
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-13
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	13
Total items failed	7

MOT #12 2023-09-25 14:43

MOT test number 798562677951

Result ✓ Passed

Next expiry date 2024-10-13

- Advice** Front brake pads approximately 50 per cent worn
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))
- Advice** Front radiator support panel heavily corroded

MOT #11 2022-09-22 15:49

MOT test number 637022207700

Result ✓ Passed

MOT #10 2021-10-14 12:22

MOT test number 219502872129

Result ✓ Passed

**MOT #9** 2021-10-13 12:48**MOT test number** 273471076669**Result** ✗ Failed

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail** Central Front Exhaust system insecure MARKED YELLOW (6.1.2 (a))

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #8** 2020-10-09 10:18**MOT test number** 122350601943**Result** ✓ Passed**MOT #7** 2020-10-01 14:52**MOT test number** 252407553265**Result** ✗ Failed

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #6** 2019-05-04 13:26**MOT test number** 428099614726**Result** ✓ Passed**MOT #5** 2019-05-04 13:26**MOT test number** 175022479142**Result** ✗ Failed

**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #4** 2018-04-27 09:18**MOT test number** 375026222089**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Oil leak
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2017-05-03 10:10**MOT test number** 127656637678**Result** ✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)

**MOT #2** 2016-05-09 10:44**MOT test number** 423032203627**Result** ✓ Passed**MOT #1** 2014-10-21 15:00**MOT test number** 467744894225**Result** ✓ Passed

- Advice** Tyre worn close to the legal limit (4.1.E.1)
- Advice** Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 January 2025

✓  
**MOT**

**Expires:**  
13 October 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	13 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-12-08
Last registration	2023-09-25
Complete history	<a href="#">See info</a>



Registration #1	2011-12-08	17 mi
Registration #2	2014-10-21	37.648 mi
Registration #3	2016-05-09	50.282 mi
Registration #4	2017-05-03	58.117 mi
Registration #5	2018-04-27	66.395 mi
Registration #6	2019-05-04	73.730 mi
Registration #7	2019-05-04	73.730 mi
Registration #8	2019-05-04	73.730 mi
Registration #9	2019-05-04	73.730 mi
Registration #10	2019-05-04	73.730 mi
Registration #11	2019-05-04	73.730 mi
Registration #12	2019-05-04	73.730 mi
Registration #13	2019-05-04	73.730 mi
Registration #14	2019-05-04	73.730 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1379 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1045425