



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM X SPORT TDCI
Colour	White
Year of manufacture	2013
Top speed	120 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-25
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-11
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	28
Total items failed	9

MOT #13	2024-04-12 10:51
MOT test number	140681800158
Result	✓ Passed
Next expiry date	2025-04-11
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12	2024-04-10 13:34
MOT test number	962660483497
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**MOT #11**

2024-04-03 10:12

MOT test number

580126482488

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #10

2023-03-27 10:17

MOT test number

700508399281

Result**✓ Passed**

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #9

2022-03-23 10:48

MOT test number

691193335815

Result**✓ Passed**

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn inner and outer edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e))

MOT #8

2021-04-07 14:24

MOT test number

654561767294

Result**✓ Passed**

**MOT #7** 2021-04-07 10:17**MOT test number** 961015513982**Result** ✗ Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #6 2019-07-08 11:33**MOT test number** 739037357521**Result** ✓ Passed

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement both trailing arm bushes badly worn (5.3.4 (a) (i))

Advice Nearside Rear Nail in tyre x2

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Rear Tyre worn close to legal limit/worn on edge both sides at 1.6mm (5.2.3 (e))

MOT #5 2018-07-13 08:06**MOT test number** 149882264602**Result** ✓ Passed

Advice Nearside Rear Nail in tyre

Advice Nearside Rear trailing arm bushe starting to seperate

Advice Offside Rear trailing arm bushe starting to seperate

**MOT #4** 2018-07-12 14:40**MOT test number** 218021967428**Result** ✗ Failed**Advice** Nearside Rear trailing arm bushe starting to seperate**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear trailing arm bushe starting to seperate**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #3** 2017-07-13 07:48**MOT test number** 327379355479**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2016-03-04 08:33**MOT test number** 779676871547**Result** ✓ Passed**MOT #1** 2016-02-27 08:47**MOT test number** 215990451495**Result** ✗ Failed**Fail** Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
11 April 2025

Tax status	Valid until 1 November
Days left	186
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-12-31
Last registration	2024-04-12
Complete history	See info



Registration #1	2013-12-31	16 mi
Registration #2	2016-02-27	22.933 mi
Registration #3	2016-03-04	23.092 mi
Registration #4	2017-07-13	33.113 mi
Registration #5	2018-07-12	44.946 mi
Registration #6	2018-07-13	44.946 mi
Registration #7	2019-07-08	55.839 mi
Registration #8	2021-04-07	69.819 mi
Registration #9	2022-05-20	75.277 mi
Registration #10	2023-05-20	75.277 mi
Registration #11	2023-05-20	75.277 mi
Registration #12	2023-05-20	75.277 mi
Registration #13	2023-05-20	75.277 mi
Registration #14	2023-05-20	75.277 mi
Registration #15	2024-04-12	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	4305 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	CY74008