





report date: 2024-03-28

### General information

Make	FORD
Model	GALAXY TITANIUM
Colour	Silver
Year of manufacture	-
Top speed	135 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	200 BHP
Max. torque	300 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

### Entry 1

Date 2021-10-09

Pictures 28

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

# **MOT** history

MOT #12	2023-08-24 08:17
MOT test number	507261466593
Result	<b>✓</b> Passed
Next expiry date	2024-08-23
MOT #11	2021-02-09 10:51

MOT test number

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10	2020-02-11 13:40
MOT test number	156617318792
Result	<b>✓</b> Passed
MOT #9	2019-02-06 10:43
MOT test number	417907131067
Result	✓ Passed

Advice Rear trailing arm bushes worn

MOT #8

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

2018-02-17 15:18

195268542581

✓ Passed

MOT #7	2017-02-18 11:18
MOT test number	876502169642
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #6 2017-02-16 16:07

**MOT test number** 194722351967

Result × Failed

**Fail** Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #5 2016-09-19 12:58

**MOT test number** 154980711220

**Result** X Failed

**Fail** Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #4** 2016-02-17 16:43

**MOT test number** 301970293143

Result 

Passed

**Advice** Nail in n/s/f tyre tread

MOT #3 2014-09-08 11:26

**MOT test number** 779631854271

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Condition of wiper blades

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2013-09-09 16:22

**MOT test number** 597022153248

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT test number

Result

Fail Offside Stop lamp not working (1.2.1b)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

ET10NWV

report date: 2024-03-28

# For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a>.

# Plate changes

More info >

More info >

CarCheck.co.uk page 8/11



ET10NWV report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



ET10NWV
report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-08-18
Last registration	2023-08-24
Complete history	See info



Registration #1	2010-08-18	13 mi
Registration #2	2013-09-09	39.688 mi
Registration #3	2013-09-09	39.688 mi
Registration #4	2014-09-08	50.069 mi
Registration #5	2016-02-17	63.447 mi
Registration #6	2016-09-19	68.108 mi
Registration #7	2017-02-16	71.181 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 10/11



ET10NWV
report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1697 kg
Max. allowed weight	2450 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11

Number of axles 2

Engine number AP42778