



TOYOTA

ROI3KYH


report date: 2024-03-28

General information

Make	TOYOTA
Model	HILUX HL3 4X4 D-4D DCB
Colour	Silver
Year of manufacture	2013
Top speed	106 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	106 kW / 144 HP / 142 BHP
Max. torque	343 Nm at 2.800 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	42.8 mpg
Consumption combined	38.7 mpg
CO2 emission	193 g/km
CO2 label	J





MOT history

MOT expiry date	2024-08-16
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	10
Total items failed	5

MOT #9	2023-07-27 08:20
MOT test number	297604952859
Result	✓ Passed
Next expiry date	2024-08-16
Advice	Brake pipe corroded, covered in grease or other material rear axle (1.1.11 (c))

MOT #8	2022-08-10 08:53
MOT test number	869826766493
Result	✓ Passed
Advice	Rear shock absorbers corroded.

MOT #7	2021-08-17 11:39
MOT test number	474798249352
Result	✓ Passed
Advice	O/S of vehicle badly damaged
Advice	Rear distribution valve bleed nipple very badly corroded

**MOT #6**

2021-08-05 15:17

MOT test number

479564411195

Result

✗ Failed

- Fail** Offside Rear Seat belt buckle not functioning as intended Not there (7.1.2 (d))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Brake pipe excessively corroded 2x front to rears to distribution valve (1.1.11 (c))
- Advice** Rear distribution valve bleed nipple very badly corroded
- Fail** Nearside Rear Seat belt buckle not functioning as intended Not there (7.1.2 (d))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** O/S of vehicle badly damaged
- Fail** Nearside Rear Brake pipe excessively corroded From distribution valve to rear flexi hose (1.1.11 (c))

MOT #5

2020-08-06 13:55

MOT test number

300010156682

Result

✓ Passed

- Advice** Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))

MOT #4

2019-03-27 11:12

MOT test number

641381744110

Result

✓ Passed

MOT #3

2018-04-06 10:12

MOT test number

864499341864

Result

✓ Passed



MOT #2	2017-03-27 09:27
MOT test number	375890006893
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1	2016-05-04 11:57
MOT test number	127502373051
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
16 August 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-04-29
Last registration	2023-07-27
Complete history	See info



Registration #1	2013-04-29	18 mi
Registration #2	2016-05-04	38.665 mi
Registration #3	2017-03-27	49.869 mi
Registration #4	2018-04-06	58.643 mi
Registration #5	2019-03-27	66.338 mi
Registration #6	2020-03-27	75.277 mi
Registration #7	2021-03-27	84.216 mi
Registration #8	2022-03-27	93.155 mi
Registration #9	2023-03-27	102.094 mi
Registration #10	2024-03-27	111.033 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1835 mm
Height	1850 mm
Length	5260 mm
Wheel base	3 mm
Kerb weight	1995 kg
Max. allowed weight	3040 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	2KDA002964