





General information

Make	AUDI
Model	A4 TDI SE
Colour	Black
Year of manufacture	2007
Top speed	125 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption


Power	115 BHP
Max. torque	285 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-06-11
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-13
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	31
Total items failed	10

MOT #17	2023-11-14 13:39
MOT test number	140786163550
Result	✓ Passed
Next expiry date	2024-11-13

MOT #16		2022-10-11 14:04
MOT test	number	646811746234
Result		✓ Passed
Advice	Rear Brake hose has slight corrosion to ferrule n/s $\&$ o/s (1.1.12 (f) (i))	
Advice	O/s/f wheel arch bubbling with corrosion.	
Advice	Front Shock absorbers has light misting of oil n/s $\&$ o/s (5.3.2 (b))	

MOT #15	2021-10-23 13:30
MOT test number	522683243788
Result	✓ Passed
Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in exercise front and rear (5.3.4 (a) (i))	cessive movement
Advice Rear Brake hose slightly deteriorated n/s and o/s (1.1.12 (b) (ii))	
Advice Offside Front wing corroded	
Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))	





MOT #14	2020-10-28 16:	12
MOT test	number 2309799742	99
Result	✓ Pass	ed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Suspension arm pin or bush worn but not resulting in excessive movement All (5.3.4 (a) (i))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	





MOT #13 2020-1	10-26 11:11
MOT test number 251	323698166
Result	🗙 Failed
Fail Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
FailOffside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Fail Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Fail Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
Fail Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8)	.2.2.2 (c))
Advice Suspension arm pin or bush worn but not resulting in excessive movement All (5.3.4 (a)	(i))
Fail Nearside Rear Service brake excessively fluctuating (1.2.1 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	





MOT #12		2019-10-19 09:47
MOT test i	number	217178525204
Result		✓ Passed
Advice	Front Shock absorbers light misting of oil or has limited damping effect o/s n	/s (5.3.2 (b))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened o/s n/s (1	L.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened o/s n/s (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin o/s n/s (1.1.13 (a) (ii))	

MOT #11	2018-10-13 09:4	6
MOT test	number 66210960854	9
Result	✓ Passe	d
Advice	Brake disc worn, pitted or scored, but not seriously weakened front/rear o/s n/s (1.1.14 (a) (ii))	
Advice	Rear Tyre slightly damaged/cracking or perishing o/s n/s (5.2.3 (d) (ii))	
Advice	Front Shock absorbers light misting of oil or has limited damping effect o/s n/s (5.3.2 (b))	

MOT #10	2017-10-26 15:52
MOT test number	461273804931
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

МОТ #9	2017-10-26 12:52
MOT test number	733018211978
Result	🗙 Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside Front Front wheel bearing rough when rotated (2.5.A.2)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #8		2016-10-26 10:03
MOT test number		156505893707
Result		✓ Passed
MOT #7		2015-10-12 09:58
MOT test number		805018391076
Result		✓ Passed
MOT #6		2014-10-15 17:01
MOT test number		629368084222
Result		✓ Passed
MOT #5		2013-11-19 11:59
MOT test number		605863323334
Result		✓ Passed
MOT #4		2012-11-01 09:00
MOT test number		416366402468
Result		✓ Passed
MOT #3		2011-11-09 09:57
MOT test number		619633811396
Result		✓ Passed
MOT #2		2010-11-24 12:08
MOT test number		192198120344
Result		× Failed
Pass with rectification	Offside Front Headlamp aim too low (1.8)	





MOT #1	2010-11-24 12:08
MOT test number	904098020338
Result	✓ Passed



Tax & MOT check

✓	✓
Taxed	MOT
Tax due:	Expires:
1 July 2024	13 November 2024
Tax status	Valid until 1 July
Days left	63
MOT expiry date	13 November 2024
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	AF I
Category	ante.
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-11-24
Last registration	2023-11-14
Complete history	<u>See info</u>



Registration #1	2007-11-24	20 mi
Registration #2	2010-11-24	14.091 mi
Registration #3	2011-11-09	19.905 mi
Registration #4	2012-11-01	25.797 mi
Registration #5	2013-11-19	32.225 mi
Registration #6	2014-10-15	38.612 mi
Registration #7	2015-10-12	48.795 mi
Registration #8	2016-10-26	58.005 mi
Registration #9	2017-10-26	66.204 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2642 mm
Kerb weight	1390 kg
Max. allowed weight	1940 kg
Additional information	
Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles	2
Engine number	BRB 043790