



report date: 2024-03-28

General information

Make	NISSAN
Model	MICRA ACENTA
Colour	Blue
Year of manufacture	2015
Top speed	100 mph
0 - 60 mph	14.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	125 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-12-22
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	19
Total items failed	0

MOT #8	2023-12-16 09:10
MOT test number	388293821570
Result	✓ Passed
Next expiry date	2024-12-22
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Non obligatory mirror damaged
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Rear Nail in tyre

MOT #7	2022-12-10 09:14
MOT test number	460769079307
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Tpms light on

**MOT #6** 2021-12-22 16:13**MOT test number** 393175569686**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Non obligatory mirror damaged**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2021-12-18 16:02**MOT test number** 587451896029**Result** ✗ Failed**Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))**MAJOR** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Non obligatory mirror damaged**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2020-12-23 11:03**MOT test number** 266975138704**Result** ✓ Passed



MOT #3	2020-07-17 11:22
MOT test number	324352298895
Result	✓ Passed
<div><div>Advice</div>NEARSIDE FRONT TYRE JUST STARTING TO GET LOW ON TREAD.CUT ON NEARSIDE FRONT OUTER TYRE WALL.</div>	

MOT #2	2019-07-24 12:49
MOT test number	704292782717
Result	✓ Passed

MOT #1	2018-08-01 10:09
MOT test number	582125754205
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
22 December 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	22 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-31
Last registration	2023-12-16
Complete history	See info



Registration #1	2015-07-31	18 mi
Registration #2	2018-08-01	12.811 mi
Registration #3	2019-07-24	15.752 mi
Registration #4	2020-07-17	17.660 mi
Registration #5	2020-12-23	18.284 mi
Registration #6	2020-12-23	18.284 mi
Registration #7	2020-12-23	18.284 mi
Registration #8	2020-12-23	18.284 mi
Registration #9	2020-12-23	18.284 mi
Registration #10	2020-12-23	18.284 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1665 mm
Height	1535 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	945 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	769327B