





report date: 2024-03-28

#### General information

Make	MAZDA
Model	CX-5 D SPORT NAV
Colour	White
Year of manufacture	2018
Top speed	127 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.600 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 2

Date 2023-03-01

Pictures 40

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

N/I	$\alpha$		IIC.	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-03-21
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #7	2024-03-07 12:35
MOT test number	420227953569
Result	<b>✓</b> Passed
Next expiry date	2025-03-21
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6	2023-03-22 12:33
MOT test number	722328033901
Result	<b>✓</b> Passed

MOT #5		2023-03-20 15:01
MOT test	number	903314400763
Result		<b>×</b> Failed
Advice	Rear Tyre slightly damaged/cracking or perishing Nearside and offside (5.2.3 (d)	(ii))
Advice	Front Tyre worn close to legal limit/worn on edge Nearside and offside (5.2.3 (e))	
Advice	Front Tyre slightly damaged/cracking or perishing Nearside and offside (5.2.3 (d)	(ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Ne	earside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3

MOT test number

446681561072

Result

Minor Front Windscreen wiper blade defective both sides (3.4 (b) (i))

MOT #2

MOT test number

444273741516

Result

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Minor Front Windscreen wiper blade defective both sides (3.4 (b) (i))

**MOT #1** 2021-01-04 16:50 **MOT** test number 465622503430 Result ✓ Passed **Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge perished in tread (5.2.3 (e)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice Advice** Nearside Front Tyre worn close to legal limit/worn on edge perished in tread (5.2.3 (e)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Rear brake discs corroded

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	21 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



LR67AHX
report date: 2024-03-28

#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-01-05
Last registration	2024-03-07
Complete history	See info



Registration #1	2018-01-05	25 mi
Registration #2	2021-01-04	24.134 mi
Registration #3		11.777 es
Registration #4	2022-01-04	33.495 mi
Registration #5	2022-01-04	33.498 mi
Registration #6		0.777-44
3		
Registration #7		11,177 es
-		11.777 es
Registration #7		11,777 est 11,777 est 11,777 est

More info >

CarCheck.co.uk page 10/11



LR67AHX
report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	78%
Safety systems	59%
Overall rating	81%
Video	see crash video



## Dimensions & weight

Width	1840 mm
Height	1680 mm
Length	4550 mm
Wheel base	2700 mm
Kerb weight	1594 kg
Max. allowed weight	2110 kg

## Additional information

Fuel tank capacity	56 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30832351

CarCheck.co.uk page 11/11