





General information

Make	RENAULT
Model	KANGOO AUTHENTIQUE 16V E4
Colour	Grey
Year of manufacture	2007
Top speed	101 mph
0 - 60 mph	12.4 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	190 g/km
CO2 label	J







Internet history

Entry 1

Date

2022-07-05

Pictures

Listing price

View report

6



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-05
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	20
Total items failed	7

MOT #17		2023-07-06 12:38
MOT test	number	297087865426
Result		✓ Passed
Next expi	ry date	2024-07-05
Advice	Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2022-07-06 09:42
MOT test number	499139616693
Result	✓ Passed

MOT #15	2021-06-29 09:21
MOT test number	316924800595
Result	🗸 Passed
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)))

MOT #14	2020-07-02 12:33
MOT test	a number 380359269869
Result	✓ Passed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Minor Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	





MOT #13	2020-06-25 09:49
MOT test number	502831293991
Result	🗙 Failed
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
FailRear Lower Exhaust system insecure (6.1.2 (a))	
Minor Offside Front Lower Windscreen damaged but not adversely affecting driver's v	view (3.2 (a) (i))
FailOffside Rear Lower Seat belt anchorage likely to become detached in the event of(a) (ii))	f a collision (7.1.1
Fail Nearside Rear Lower Integral body structure corroded to the extent that the rigid is significantly reduced loading ramp. (6.1.1 (c) (i))	ity of the assembly
Advice Nearside Rear under wing shield insecure rubbing tyre.	
FailNearside Rear Lower Seat belt anchorage likely to become detached in the event(a) (ii))	of a collision (7.1.1
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriora	ted (6.1.7 (g) (i))
MOT #12	2019-04-11 08:26

2019-04-11 08:26
613096265293
✓ Passed

MOT #11	2018-04-20 12:53
MOT test number	581219032331
Result	Passed
Advice Central Exhaust has a minor leak of exhaust gases centre joint Also through in places making it very weak. (7.1.2)	o support/clamp is rusted

Advice Nearside Rear Slight brake bind.



MOT #10

RX57CDU
report date: 2024-03-29
2018-04-20 08:12
380116714409

MOT test	number	380116714409
Result		🗙 Failed
 Advice Nearside Rear Slight brake bind. Advice Central Exhaust has a minor leak of exhaust gases centre joint Also support/clamp is rusted through in places making it very weak. (7.1.2) Fail Nearside Front Lower Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2) 		
MOT #9		2017-04-25 08:24
MOT test number 320604462319		320604462319
Result		✓ Passed
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)		'A' (8.3.1a)

МОТ #8	2016-04-07 09:15
MOT test number	722373841319
Result	✓ Passed

MOT #7	20	15-04-20 15:10
MOT test	number	237750715483
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nearside rear tyre perishing	

МОТ #6	2014-04-26 10:06
MOT test number	698016914129
Result	✓ Passed
Notice Nearside front tyre perished	



MOT #5		2014-04-22 14:37
MOT test	number	125892914197
Result		× Failed
Notice	Nearside front tyre is badly cracked/ perished and worn low	
Notice	Nearside rear tyre is badly cracked/ perished	
Fail 0 (4.1.D.1a)	ffside Rear Tyre has a cut in excess of the requirements deep enough to	reach the ply or cords

MOT #4	2013-10-07 12:22
MOT test number	885100283281
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #3	2012-09-26 12:51
MOT test number	448940772267
Result	✓ Passed
MOT #2	2011-10-03 12:23
MOT test number	368886571482
Result	✓ Passed
MOT #1	2010-09-21 12:55
MOT test number	283374460210

	# 1	2010-05-21 12.55
МОТ	test number	283374460210
Resu	lt	✓ Passed

RX57CDU

report date: 2024-03-29



Tax & MOT check

Tax due:	√ Taxed	Expires: 5 July 2024	✓ MOT
1 August 2024 Tax status		5 July 2024	Valid until 1 August
Days left			95
MOT expiry date			5 July 2024
Full MOT history			See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4 ARAPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-10-09
Last registration	2023-07-06
Complete history	<u>See info</u>



Registration #1	2007-10-09	21 mi
Registration #2	2010-09-21	11.110 mi
Registration #3	2011-10-03	13.010 mi
Registration #4	2012-09-26	14.871 mi
Registration #5	2013-10-07	16.222 mi
Registration #6	2014-04-22	17.310 mi
Registration #7	2014-04-26	17.322 mi
Registration #8	2015-04-20	19.613 mi
Registration #9	2016-04-07	22.096 mi
Registration #10	2017-04-25	25.035 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 est





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2605 mm
Kerb weight	1120 kg
Max. allowed weight	1645 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13