



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	VERSO VALVEMATIC TR
Colour	Blue
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	132 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-31
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	19
Total items failed	8

MOT #17 2024-01-15 11:42

MOT test number 888994294548

Result ✓ Passed

Next expiry date 2025-01-31

- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both Sides (5.3.4 (a) (i))
- Advice** Front Suspension arm corroded but not seriously weakened Both Sides (5.3.3 (b) (i))

MOT #16 2023-02-01 16:40

MOT test number 776448937531

Result ✓ Passed

- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Both Sides (5.3.4 (a) (i))
- Advice** Under Body Seal
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #15 2021-12-21 12:59

MOT test number 591668596346

Result ✓ Passed

**MOT #14** 2021-12-10 14:32**MOT test number** 838449871512**Result** ✗ Failed**Fail** Horn not working (7.7 (a))**MOT #13** 2021-03-19 13:21**MOT test number** 925751643631**Result** ✓ Passed**MOT #12** 2021-03-19 13:21**MOT test number** 297369571078**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2019-12-10 17:22**MOT test number** 295225743261**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Front Exhaust mounting defective (6.1.2 (a))

**MOT #10** 2019-12-10 08:31**MOT test number** 438125614695**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Central Front Exhaust mounting defective (6.1.2 (a))**MOT #9** 2018-11-02 15:50**MOT test number** 860819194648**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))**MOT #8** 2018-11-02 08:21**MOT test number** 566031734319**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Brake pipe excessively corroded to rear, nearside front & both rear (4 (1.1.11 (c))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**MOT #7** 2017-11-24 08:20**MOT test number** 370298275131**Result** ✓ Passed**Advice** Tyre worn close to the legal limit Both rear (4.1.E.1)

**MOT #6** 2016-11-18 14:12**MOT test number** 563187407537**Result** ✓ Passed**MOT #5** 2016-11-18 07:34**MOT test number** 762795011273**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2015-12-11 13:18**MOT test number** 257157285222**Result** ✓ Passed**MOT #3** 2014-12-19 08:07**MOT test number** 866233954341**Result** ✓ Passed**MOT #2** 2013-12-17 08:11**MOT test number** 629161253319**Result** ✓ Passed**MOT #1** 2012-12-08 09:31**MOT test number** 907353842371**Result** ✓ Passed**Advice** Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
31 January 2025

Tax status	Valid until 1 November
Days left	185
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-12-30
Last registration	2024-01-15
Complete history	See info



Registration #1	2009-12-30	10 mi
Registration #2	2012-12-08	36.222 mi
Registration #3	2013-12-17	52.333 mi
Registration #4	2014-12-19	58.685 mi
Registration #5	2015-12-11	66.311 mi
Registration #6	2016-11-18	73.549 mi
Registration #7	2016-11-18	73.549 mi
Registration #8	2017-11-24	77.609 mi
Registration #9	2018-11-02	82.102 mi
Registration #10	2018-11-02	82.102 mi
Registration #11	2019-05-29	85.377 mi
Registration #12	2019-05-29	85.377 mi
Registration #13	2019-05-29	85.377 mi
Registration #14	2019-05-29	85.377 mi
Registration #15	2019-05-29	85.377 mi
Registration #16	2019-05-29	85.377 mi
Registration #17	2019-05-29	85.377 mi
Registration #18	2019-05-29	85.377 mi
Registration #19	2019-05-29	85.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1505 kg
Max. allowed weight	2125 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number 1ZSU191958