



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Silver
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history****MOT #15** 2023-04-17 09:20**MOT test number** 374497924733**Result** ✗ Failed

- Fail** Axle fractured (5.1.1 (a))
- Fail** Offside Rear Coil spring mounting corroded and seriously weakened axle (5.3.1 (b) (i))
- Fail** Nearside Rear Coil spring mounting corroded and seriously weakened axle (5.3.1 (b) (i))

**MOT #14** 2022-02-05 09:57**MOT test number** 122847938855**Result** ✓ Passed

- Advice** Rear subframe corroded
- Advice** Coil spring corroded both rears (5.3.1 (b) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2022-02-04 10:34**MOT test number** 895669305942**Result** ✗ Failed

- Advice** Nearside Front bumper loose but not likely to become detached
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Headlamp insecure (4.1.1 (c))
- Advice** Rear subframe corroded
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Coil spring corroded both rears (5.3.1 (b) (i))

**MOT #12** 2021-01-29 17:23**MOT test number** 977148295079**Result** ✓ Passed**MOT #11** 2021-01-29 09:24**MOT test number** 771304288226**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #10** 2020-06-05 09:06**MOT test number** 493383282181**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner surfaces (1.1.14 (a) (ii))**MOT #9** 2019-06-14 08:10**MOT test number** 349172997388**Result** ✓ Passed**MOT #8** 2018-06-01 15:26**MOT test number** 835701244211**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2017-05-23 15:32**MOT test number** 951528675233**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit both sides (4.1.E.1)**MOT #6** 2017-05-23 10:11**MOT test number** 806795007994**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively split (8.2.2)**Fail** Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)**Fail** Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)**Advice** Rear Tyre worn close to the legal limit both sides (4.1.E.1)**MOT #5** 2016-05-13 15:22**MOT test number** 604552653015**Result** ✓ Passed**Advice** Exhaust tail box corroded**Advice** Front Exhaust has a minor leak of exhaust gases flexi joint (7.1.2)**MOT #4** 2015-05-18 11:28**MOT test number** 955118335187**Result** ✓ Passed**Notice** Exhaust tailbox corroded**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #3	2014-05-22 11:02
MOT test number	518322344167
Result	✓ Passed
Notice	Exhaust tailbox corroded
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-05-15 11:05
MOT test number	919715333115
Result	✓ Passed
Notice	Exhaust tailbox corroded

MOT #1	2012-04-30 15:50
MOT test number	989351122105
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-05-22
Last registration	2023-04-17
Complete history	<a href="#">See info</a>



Registration #1	2009-05-22	9 mi
Registration #2	2012-04-30	31.091 mi
Registration #3	2013-05-15	37.742 mi
Registration #4	2014-05-22	46.298 mi
Registration #5	2015-05-18	56.120 mi
Registration #6	2016-05-13	64.586 mi
Registration #7	2017-05-23	76.599 mi
Registration #8	2017-05-23	76.599 mi
Registration #9	2018-06-01	87.791 mi
Registration #10	2019-05-22	95.120 mi
Registration #11	2020-05-22	102.450 mi
Registration #12	2021-05-22	109.780 mi
Registration #13	2022-05-22	117.110 mi
Registration #14	2023-05-22	124.440 mi
Registration #15	2024-05-22	131.770 mi
Registration #16	2025-05-22	139.100 mi
Registration #17	2026-05-22	146.430 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	5187434