



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	PRIUS VVT-I T4
Colour	Blue
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed CVT

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-14
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-03
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	62
Total items failed	8

MOT #202023-12-04 11:41

MOT test number748981517158

Result✓ Passed

Next expiry date2024-12-03

- Advice** Under vehicle cover with under seal
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Suspension component corroded but not seriously weakened front and rear both sides (5.3.3 (b) (i))
- Advice** Nearside Rear Fuel Pipe/s corroded
- Advice** Head lights have poor beam
- Advice** Coil spring corroded all (5.3.1 (b) (i))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive front and rear (5.3.6 (a) (i))

**MOT #19**

2023-06-17 13:57

MOT test number

624614898006

Result

✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Under vehicle has been under sealed
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn Both sides (5.1.2 (b) (i))

MOT #18

2022-12-19 14:12

MOT test number

125870259489

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front and rear subframe and suspension arms corroded
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear both side radius arm bush worn
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Both side sills and mounting area corroded

**MOT #17**

2022-06-20 12:43

MOT test number

822507004910

Result

✓ Passed

- Advice** Offside Front tyre slightly worn low
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Both side headlamp have poor beam
- Advice** Coil spring corroded all (5.3.1 (b) (i))
- Advice** Under vehicle covered in under seal

MOT #16

2021-12-21 13:33

MOT test number

708757915294

Result

✓ Passed

- Advice** Rear axel bush slightly worn
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Under vehicle suspension component's corroded

MOT #15

2021-06-28 15:00

MOT test number

809464496628

Result

✓ Passed

- Advice** Front Suspension arm corroded but not seriously weakened Both sides (5.3.3 (b) (i))
- Advice** Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Under vehicle has been under sealed

MOT #14

2021-06-09 15:22

MOT test number

805900764850

Result

✓ Passed

**MOT #13**

2020-09-03 16:10

MOT test number

454357718114

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Various mechanical components corroded on underside of vehicle**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12**

2020-08-27 15:45

MOT test number

252554589557

Result

✗ Failed

Fail Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))**Advice** Various mechanical components corroded on underside of vehicle**MOT #11**

2019-09-05 09:21

MOT test number

463098345938

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2018-09-04 16:54

MOT test number

837362120738

Result

✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #9

2018-09-03 14:09

MOT test number

238798607244

Result

✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively torn (3.4 (b) (ii))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))

MOT #8

2017-09-05 15:19

MOT test number

730855184935

Result

✓ Passed

- Advice** Emissions not tested due to hybrid

**MOT #7** 2016-08-24 10:18**MOT test number** 465853439131**Result** ✓ Passed**Advice** Rear brake discs corroded**Advice** Offside Rear tyre perished**MOT #6** 2015-08-27 14:27**MOT test number** 189669735206**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2014-09-03 12:39**MOT test number** 855436144280**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2013-09-06 13:32**MOT test number** 347299943231**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #3** 2013-09-06 13:32**MOT test number** 306299943212**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-08-28 10:12**MOT test number** 327471842224**Result** ✓ Passed**MOT #1** 2011-08-30 10:35**MOT test number** 356552841430**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
3 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	3 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-01
Last registration	2023-12-04
Complete history	See info



Registration #1	2008-09-01	20 mi
Registration #2	2011-08-30	45.266 mi
Registration #3	2012-08-28	58.532 mi
Registration #4	2013-09-06	64.093 mi
Registration #5	2014-09-03	28.352 mi
Registration #6	2015-08-27	71.175 mi
Registration #7	2016-08-24	74.831 mi
Registration #8	2017-09-05	79.129 mi
Registration #9	2018-09-03	83.303 mi
Registration #10	2018-09-04	83.318 mi
Registration #11	2019-09-05	88.365 mi
Registration #12	2020-09-05	93.412 mi
Registration #13	2021-09-05	98.459 mi
Registration #14	2022-09-05	103.506 mi
Registration #15	2023-09-05	108.553 mi
Registration #16	2023-12-04	113.600 mi
Registration #17		
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1325 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1NZ5248639