





### General information

Make	FIAT
Model	500 C C LOUNGE
Colour	White
Year of manufacture	2013
Top speed	99 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	69 BHP	
Max. torque	102 Nm at 3.500 rpm	0 < 101 A
Engine capacity	1.242 cc	101 - 120 B 121 - 140 P
Cylinders	4	141 - 165
Fuel type	Petrol	166 - 185
Consumption city	44.1 mpg	186 - 225
Consumption extra urban	65.7 mpg	225+
Consumption combined	55.4 mpg	
CO2 emission	113 g/km	
CO2 label	С	





# Internet history Entry 4 Date 2023-12-06 Pictures 0

Listing price

# source: carcraft.co.uk

Er	ntry	3	

Date	2023-11-18	
Pictures	41	
Listing price	View report	

View report



#### source: cargurus.co.uk

Entry 2	
Date	2021-12-02
Pictures	12
Listing price	View report







source: cargurus.co.uk

Entry 1	
Date	2021-12-01
Pictures	41
Listing price	View report









source: autotrader.co.uk



# MOT history

MOT expiry date	2024-12-27
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	27
Total items failed	0

MOT #10	2023-12-28 13:16
MOT test number	184027240383
Result	✓ Passed
Next expiry date	2024-12-27

MOT #9		2023-12-21 13:41
MOT test	number	344249044879
Result		🗙 Failed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
MAJOR	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1	2 (c))
Advice	Coolant leak	

МОТ #8	2023-02-13 11:28
MOT test number	797976608243
Result	✓ Passed
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	





MOT #7		2021-12-09 09:13
MOT test	number	371388263775
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

MOT #6	2021-02-01 14:09
MOT test number	553046960705
Result	✓ Passed
Advice O/s/r light lens damaged	

MOT #5		2021-01-27 11:42
MOT test	number	899376403908
Result		🗙 Failed
MAJOR	Rear Registration plate insecure (0.1 (a))	
Advice	Oil leak, but not excessive sump heavly corroded and just starting to leak (8.4	4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
MAJOR	Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Advice	Day time running lights not working	
MAJOR	Exhaust silencer insecure rear exhaust clamp missing (8.1.1 (b) (i))	
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice	O/s/r light lens damaged	

МОТ #4	2019-07-23 10:35
MOT test number	809676873707
Result	✓ Passed



<b>CP13KGE</b>
report date: 2024-03-29

МОТ #3	2018-07-17 14:22
MOT test number	689928225111
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Rear Coil spring corroded n/s & o/s (5.3.1 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened n/s & o	/s (1.1.14 (a) (ii))

MOT #2	2018-07-16 11:46
MOT test number	442150183167
Result	× Failed
Advice Rear Coil spring corroded n/s & o/s (5.3.1 (b) (i))	
<b>DANGEROUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	)
Advice Front Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1	.1.14 (a) (ii))
Advice Offside Rear Nail in tyre	
<b>DANGEROUS</b> Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
<b>DANGEROUS</b> Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #1	2017-	07-25 08:06
MOT test	number 23	8553978408
Result		🗸 Passed
Advice	N/s/r Tyre wearing outer edge but tread not cut as deep	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	



Tax & MOT check

<b>Tax due:</b> 1 January 2025	✓ Taxed	<b>Expires:</b> 27 December 2024	✓ МОТ
Tax status			Valid until 1 January
Days left			246
MOT expiry date			27 December 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	
************	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-08-10
Last registration	2023-12-28
Complete history	See info



Registration #1	2013-08-10	16 mi
Registration #2	2017-07-25	38.426 mi
Registration #3	2018-07-16	45.732 mi
Registration #4	2018-07-17	45.732 mi
Registration #5	2019-07-23	54.825 mi
Registration #6	2021-01-27	88.886 mi
Registration #7	2021-02-01	88.888 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	905 kg
Max. allowed weight	1320 kg
Additional information	
Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	0484876