



AJ57ZTL

report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC 136
Colour	Red
Year of manufacture	2008
Top speed	125 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	149 g/km
CO2 label	F





MOT history

MOT expiry date	2021-03-13
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	28
Total items failed	23

MOT #15	2020-03-12 13:57
MOT test number	119950110373
Result	✓ Passed
Next expiry date	2021-03-13
Advice	Engine oil leak
Advice	Exhaust back box corroded not leaking

**MOT #14**

2020-03-11 13:14

MOT test number

247392951763

Result

✗ Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Rear Rear reflector missing (4.8.2 (a) (ii))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Direction indicator not working Side indicator lamp missing (4.4.1 (a) (ii))

Fail Nearside Front Position lamp not working Side light (4.2.1 (a) (ii))

Fail Vehicle Identification Number incomplete Broken (0.2 (b))

Advice Exhaust back box corroded not leaking

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Engine oil leak

MOT #13

2019-03-14 17:26

MOT test number

787822637695

Result

✓ Passed

Advice Offside Front Nail in tyre

Advice Brake pedal wearing smooth (1.1.2 (c))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))

**MOT #12**

2019-03-14 17:26

MOT test number

415131337907

Result**✗ Failed****Advice**

Offside Front Nail in tyre

Advice

Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Brake pedal wearing smooth (1.1.2 (c))

Pass with rectification

Front Headlamp not working on dipped beam Both sides (4.1.1 (a) (ii))

MOT #11

2017-04-28 10:36

MOT test number

317347267282

Result**✓ Passed****Advice**

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10**

2017-04-13 14:30

MOT test number

567031793883

Result**✗ Failed**

- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)
- Fail** Offside Rear reflector missing (1.5.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #9

2016-02-12 10:45

MOT test number

940284416736

Result**✓ Passed**

- Advice** Rear Tyre worn close to the legal limit Both (4.1.E.1)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2015-02-06 10:19**MOT test number** 208117735015**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-01-15 15:05**MOT test number** 195635414411**Result** ✓ Passed**Notice** Oil leak**MOT #6** 2014-01-15 15:05**MOT test number** 919745214086**Result** ✗ Failed**Notice** Oil leak**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2013-01-31 09:49**MOT test number** 337331733041**Result** ✓ Passed**MOT #4** 2013-01-25 12:37**MOT test number** 457115423060**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)



MOT #3	2012-01-11 12:33
MOT test number	446601612080
Result	✓ Passed
MOT #2	2011-01-22 09:30
MOT test number	548142121042
Result	✓ Passed
MOT #1	2011-01-17 10:39
MOT test number	527367711094
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
6 January 2021

X

MOT

Expired:
13 March 2021

Tax status	Expired at 6 January 2021
Days left	1209 days too late
MOT expiry date	13 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-01-19
Last registration	2020-03-12
Complete history	See info



Registration #1	2008-01-19	11 mi
Registration #2	2011-01-17	53.203 mi
Registration #3	2011-01-22	53.536 mi
Registration #4	2012-01-11	75.814 mi
Registration #5	2013-01-25	104.644 mi
Registration #6	2013-01-31	104.952 mi
Registration #7	2014-01-15	128.898 mi
Registration #8	2015-02-06	133.578 mi
Registration #9	2015-05-20	151.377 mi
Registration #10	2015-05-20	151.377 mi
Registration #11	2015-05-20	151.377 mi
Registration #12	2015-05-20	151.377 mi
Registration #13	2015-05-20	151.377 mi
Registration #14	2015-05-20	151.377 mi
Registration #15	2015-05-20	151.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Max. allowed weight	1990 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

8G46203