



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Red
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A





## MOT history

MOT expiry date	2025-04-24
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	22
Total items failed	9

## MOT #15 2024-04-25 13:43

MOT test number 331305017771

Result ✓ Passed

Next expiry date 2025-04-24

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

## MOT #14 2023-02-14 15:15

MOT test number 734155230307

Result ✓ Passed

## MOT #13 2023-02-14 15:15

MOT test number 585255247704

Result ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

## MOT #12 2022-02-10 16:35

MOT test number 391256162869

Result ✓ Passed

**MOT #11** 2021-01-21 09:37**MOT test number** 228697578811**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2021-01-21 09:37**MOT test number** 451362683655**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Rear Upper Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2020-02-12 10:37**MOT test number** 202005827648**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #8** 2019-02-15 16:18**MOT test number** 230939228585**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7**

2019-02-13 11:33

**MOT test number**

426895417233

**Result****✗ Failed****Advice** Front Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6**

2018-02-14 15:01

**MOT test number**

412024336113

**Result****✓ Passed****Advice** Nearside Rear Inner badly worn inside edge but no cords/ plys showing**MOT #5**

2017-02-15 12:38

**MOT test number**

441352108587

**Result****✓ Passed****Advice** Engine covers and under trays fitted**Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #4**

2017-02-14 16:20

**MOT test number**

792841811959

**Result****✗ Failed****Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Engine covers and under trays fitted**Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #3** 2016-03-22 12:02**MOT test number** 907058978805**Result** ✓ Passed**MOT #2** 2015-02-12 14:07**MOT test number** 988043545015**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-02-12 12:10**MOT test number** 909643945070**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
24 April 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	24 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>VO12KUH</b>
Plate since	2019-09-28
Current registration	<b>VO12KUH</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-01
Last registration	2024-04-25
Complete history	<a href="#">See info</a>



Registration #1	2012-03-01	14 mi
Registration #2	2015-02-12	75.762 mi
Registration #3	2015-02-12	75.762 mi
Registration #4	2016-03-22	86.923 mi
Registration #5	2017-02-14	94.376 mi
Registration #6	2017-02-15	94.381 mi
Registration #7	2018-02-14	104.497 mi
Registration #8	2019-02-13	114.949 mi
Registration #9	2019-02-13	114.949 mi
Registration #10	2019-02-13	114.949 mi
Registration #11	2019-02-13	114.949 mi
Registration #12	2019-02-13	114.949 mi
Registration #13	2019-02-13	114.949 mi
Registration #14	2019-02-13	114.949 mi
Registration #15	2019-02-13	114.949 mi
Registration #16	2019-02-13	114.949 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2041867