





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	CLK CLK230 K SPORT
Colour	Blue
Year of manufacture	-
Top speed	141 mph
0 - 60 mph	8.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	280 Nm at 2.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	19.1 mpg
Consumption extra urban	35.8 mpg
Consumption combined	27.2 mpg



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-10-21

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT #15 2016-04-29 07:56

MOT test number 787693840156

Result ✓ Passed

Next expiry date 2017-04-28

Advice Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)

Advice Nearside Rear tyre on limit

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pipe slightly corroded of both main (3.6.B.2c)

Advice Offside Front tyre on limit

MOT #14 2016-04-28 12:13

MOT test number 881703693258

Result X Failed

Fail Registration plate lamp not working both (1.1.C.1d)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Advice Nearside Rear tyre on limit

Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front tyre on limit

Advice Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)

Advice Rear Brake pipe slightly corroded of both main (3.6.B.2c)

MOT #13 2014-11-05 17:25

MOT test number 865309904394

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 3/11



S334TYC

report date: 2024-03-28

MOT #12 2014-10-28 16:41

MOT test number 435511704392

Result X Failed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

MOT #11 2013-10-30 10:22

MOT test number 418533003371

Result
✓ Passed

MOT #10 2012-11-17 11:40

MOT test number 407502622468

Result \rightarrow Passed

MOT #9 2011-11-22 08:41

MOT test number 886876721364

MOT #8 2010-11-08 11:07

MOT test number 652262010394

Result

Passed

Notice N/S Front fog lamp damaged

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #7 2009-11-09 10:05

MOT test number 201153619321

Result

Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 4/11



Pass with rectification

S334TYCreport date: 2024-03-28

MOT #6 2008-11-19 16:50 421234428415 **MOT test number** Result ✓ Passed MOT #5 2008-11-18 09:50 **MOT** test number 401113128375 Result × Failed Fail Offside Front coil spring cracked (2.4.C.1a) **Advice** Nearside Rear brake disc slightly pitted (3.5.1h) Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Advice Offside Rear brake disc slightly pitted (3.5.1h)

MOT #4	2007-12-10 17:04
MOT test number	560524747381
Result	✓ Passed
MOT #3	2007-06-18 17:29
MOT test number	130409867143
Result	✓ Passed
MOT #2	2006-05-23 16:53
MOT test number	471973746101
Result	✓ Passed
MOT #1	2006-05-23 16:53
MOT test number	954153746198
Result	X Failed

CarCheck.co.uk page 5/11

Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Damage 2

Date

Type

Category

Type



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	1998-12-11
Last registration	2016-04-29
Complete history	See info



Registration #1	1998-12-11	17 mi
Registration #2	2006-05-23	92.051 mi
Registration #3	2007-06-18	95.806 mi
Registration #4	2007-12-10	99.100 mi
Registration #5	2008-11-18	103.462 mi
Registration #6	2008-11-19	103.462 mi
Registration #7	2009-11-09	107.242 mi
Registration #8	2010-11-08	109.819 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
0567	
60569	
iew the complete MERCEDES-BENZ factory list for this	More info >

				~			
ונו	men:	CIOT	nc -	λ.	WAI	α	ht.
וט	пеп	STUI	13	CX.	$VV \subset I$	ш	TTU.

Width	1722 mm
Height	1345 mm
Length	4567 mm
Kerb weight	1350 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	010869

CarCheck.co.uk page 11/11