





report date: 2024-03-29

### General information

Make	MAZDA
Model	5 D SPORT NAV
Colour	Black
Year of manufacture	2012
Top speed	111 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/12



## Internet history

### Entry 1

Date 2021-10-08

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-05
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #13		2023-10-06 17:24
MOT test	number	855875960964
Result		✓ Passed
Next expi	ry date	2024-10-05
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2023-10-06 16:03
MOT test number	270398431854
Result	<b>X</b> Failed
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Brake performance unable to be tested (1.2.1 (g))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #11 2022-09-29 10:03

**MOT test number** 444175853306

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Hole in n/s/r light lense not showing white to front or rear

**MOT #10** 2022-09-21 15:36

**MOT test number** 558097811734

**Result** X Failed

**Advice** Hole in n/s/r light lense not showing white to front or rear

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #9** 2021-10-06 08:59

**MOT test number** 572096843996

**Result** ✓ Passed

MOT #8 2021-03-09 18:27

**MOT test number** 706465232966

**Result** ✓ Passed

MOT #7 2020-08-11 12:17

**MOT test number** 692020037049

**Result** ✓ Passed

CarCheck.co.uk page 4/12



**MOT #4** 

WN12NZJ

report date: 2024-03-29

2018-04-30 10:46

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Reversing lamp inoperative (4.6.1 (a))

MOT test number

Fesult

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number	446003224722
Result	<b>✓</b> Passed
MOT #3	2017-04-25 09:00
MOT test number	888428414041
Result	<b>✓</b> Passed
Advice Front wipers smearing	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 5/12



MOT test number

S58169871101

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2015-05-07 10:18
MOT test number	745457725129
Result	✓ Passed

CarCheck.co.uk page 6/12



### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	biotom
UMMINAI	nisiaiv
OVVIICI	IIIJCOI Y

o mile mesery		
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full		Α
manuscope de la companya della companya della companya de la companya de la companya della compa		
***************************************		
***************************************		
THE PERSON NAMED IN COLUMN TO THE PE		
	More info	>
Plate changes		
See in this check if this MAZDA had different number plates.		
Number of plates		
Current registration	NK SIE	
Plate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-26
Last registration	2023-10-06
Complete history	See info



Registration #1	2012-06-26	23 mi
Registration #2	2015-05-07	21.695 mi
Registration #3	2016-05-03	38.046 mi
Registration #4	2017-04-25	53.280 mi
Registration #5	2018-04-30	68.013 mi
Registration #6	2019-04-09	79.281 mi
Registration #7	2020-08-07	96.246 mi
Registration #8	2020-08-11	96.246 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1750 mm
Height	1615 mm
Length	4585 mm
Wheel base	2750 mm
Kerb weight	1490 kg
Max. allowed weight	2125 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Indirect Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	Y6 347264

CarCheck.co.uk page 12/12