



FY63FRF

report date: 2024-03-29

General information

| | |
|---------------------|--------------------|
| Make | MINI |
| Model | MINI COOPER D ALL4 |
| Colour | Blue |
| Year of manufacture | 2013 |
| Top speed | 112 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|----------------------|---------------------|
| Power | 112 BHP |
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption combined | 64.2 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-14 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-27 |
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 14 |
| Total items failed | 2 |

| | |
|------------------|--|
| MOT #11 | 2023-10-19 09:02 |
| MOT test number | 937702798859 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-27 |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|-------------------------|--|
| MOT #10 | 2023-10-19 09:02 |
| MOT test number | 170104767939 |
| Result | ✗ Failed |
| Pass with rectification | Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|-----------------|---|
| MOT #9 | 2022-10-27 07:54 |
| MOT test number | 971140056850 |
| Result | ✓ Passed |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e)) |

**MOT #8** 2021-10-01 11:42**MOT test number** 755382196835**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2020-10-28 12:19**MOT test number** 234754233241**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-10-21 15:50**MOT test number** 470139091226**Result** ✓ Passed**MOT #5** 2018-10-23 11:08**MOT test number** 847923771772**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin rear brake pads thin (1.1.13 (a) (ii))**Advice** Offside Rear Nail in tyre**Advice** Offside Front Inner osf tyre worn inner edge

**MOT #4** 2018-10-20 14:03**MOT test number** 835607530159**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords nsf
tyre has cut in tread down to cords (5.2.3 (d) (i))**Advice** Offside Front Inner osf tyre worn inner edge**Advice** Rear Brake pad(s) wearing thin rear brake pads thin (1.1.13 (a) (ii))**Advice** Offside Rear Nail in tyre**MOT #3** 2017-10-21 08:14**MOT test number** 919022114920**Result** ✓ Passed**Advice** Central Front Items removed from driver's view prior to test**MOT #2** 2016-09-30 10:47**MOT test number** 929074956700**Result** ✓ Passed**MOT #1** 2016-05-31 16:14**MOT test number** 221036992316**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
27 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 247 |
| MOT expiry date | 27 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MINI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2013-09-27 |
| Last registration | 2023-10-19 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-09-27 | 20 mi |
| Registration #2 | 2016-05-31 | 24.950 mi |
| Registration #3 | 2016-09-30 | 27.341 mi |
| Registration #4 | 2017-10-21 | 34.112 mi |
| Registration #5 | 2018-10-20 | 41.667 mi |
| Registration #6 | 2018-10-23 | 41.683 mi |
| Registration #7 | 2019-10-21 | 48.959 mi |
| Registration #8 | 2020-05-20 | 55.277 mi |
| Registration #9 | 2020-05-20 | 55.277 mi |
| Registration #10 | 2020-05-20 | 55.277 mi |
| Registration #11 | 2020-05-20 | 55.277 mi |
| Registration #12 | 2020-05-20 | 55.277 mi |
| Registration #13 | 2020-05-20 | 55.277 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1789 mm |
| Height | 1577 mm |
| Length | 4097 mm |
| Kerb weight | 1380 kg |
| Max. allowed weight | 1890 kg |

Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number | 71018432 |