





General information

| Make | VOLVO |
|---------------------|-----------------|
| Model | V40 T2 MOMENTUM |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 118 mph |
| 0 - 60 mph | 9.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 121 BHP | 0 < 101 A |
|----------------------|---------------------|-------------------------------------|
| Max. torque | 220 Nm at 1.200 rpm | 101 - 120 ^B _C |
| Engine capacity | 1.969 cc | 121 - 140 D |
| Cylinders | 4 | 141 - 165 F G |
| Fuel type | Petrol | 166 - 185 H |
| Consumption combined | 2.8 mpg | 186 - 225 J |
| CO2 emission | 137 g/km | 225+ L |
| CO2 label | E | |





Internet history

| Entry 2 | |
|---------------|--------------------|
| Date | 2021-06-28 |
| Pictures | 10 |
| Listing price | <u>View report</u> |



source: autoonline.co.uk

| Entry 1 | | |
|---------------|-------------|-------------|
| Date | 2021-06-18 | |
| Pictures | 5 | |
| Listing price | View report | |
| Ziverside | | YOUR safety |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-06-17 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 1 |

| MOT #4 | | 2023-06-12 14:11 |
|-----------|--|------------------|
| MOT test | number | 715568888945 |
| Result | | 🗸 Passed |
| Next expi | ry date | 2024-06-17 |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

MOT #3 2022-06-09 08:51 MOT test number 457275987820 Result Passed

| MOT #2 | 2021-06-02 16:05 |
|---|------------------|
| MOT test number | 377402715482 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |





| MOT #1 | 2021-06-02 10:23 |
|---|------------------|
| MOT test number | 793458894616 |
| Result | 🗙 Failed |
| FailOffside Front Coil spring fractured or broken (5.3.1 (b) (i))AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |



Tax & MOT check

| ✓ Taxed | ✓ MOT |
|-------------------------|--------------------------|
| Tax due: 1 July 2024 | Expires: 17 June 2024 |
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 17 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | FE CO |
| Category | Lashe |
| Туре | |
| Damage 2 | AMPLE |
| Damaye 2 | e e et al |
| Date | 1. |
| Category | AMP |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-06-18 |
| Last registration | 2023-06-12 |
| Complete history | See info |



| Registration #1 | 2018-06-18 | 27 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-06-02 | 19.584 mi |
| Registration #3 | 2021-06-02 | 19.584 mi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| \$0482 | |
| S0501 | |
| \$0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 98% |
| Children | 75% |
| Pedestrian | 88% |
| Safety systems | 100% |
| Overall rating | 92% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1857 mm |
| Height | 1439 mm |
| Length | 4369 mm |
| Wheel base | 2647 mm |
| Kerb weight | 1393 kg |
| Max. allowed weight | 1965 kg |
| Additional information | |
| Fuel tank capacity | 62 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | 2630091 |