





General informationMakeLAND ROVERModelDEFENDER HARD TOPColourGreenYear of manufacture2003Gearbox6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	360 Nm at 2.200 rpm
Engine capacity	2.495 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.2 mpg
Consumption extra urban	32.8 mpg
Consumption combined	27.4 mpg





Internet history

Entry 4

Date Pictures 2022-05-19

12

Listing price

View report



source: cargurus.co.uk

Date

Pictures

Listing price

2021-09-05 12

View report



source: cargurus.co.uk

Entry 2	
Date	2021-08-09
Pictures	16
Listing price	View report



source: autotrader.co.uk

Entry 1
Date
Pictures CarCheck.co.uk

2021-07-04


Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-23	
MOT pass rate	58 %	
MOT passed	7	
Failed MOT tests	5	
Total advice items	17	
Total items failed	12	

MOT #12	2024-04-18 08:03	
MOT test number	135501059076	
Result	🗙 Failed	
Fail Offside Rear Position lamp adversely affected by the operation of another by brake lamp (4.2.3 (c))	lamp Position lamp affected	
Fail Nearside Front Track rod end ball joint has excessive play Foremost (2.1.3)	(b) (i))	
Fail Offside Front Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt Steering box arm (2.1.3 (g) (ii))		
Advice Coolant low level		

MOT #11		2023-04-24 11:33
MOT test	t number	420437989053
Result		✓ Passed
Minor preventin	Offside Front Steering linkage ball joint ball joint dust cover damaged or ng the ingress of dirt (2.1.3 (g) (i))	deteriorated, but





MOT #10	2023-04-17 12:03
MOT test number	248996114574
Result	🗙 Failed
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Minor Offside Front Steering linkage ball joint ball joint dust cover damaged of preventing the ingress of dirt (2.1.3 (g) (i))	r deteriorated, but
FailOffside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Windscreen washer jets misaligned and not providing sufficient fluid to the	e windscreen (3.5 (a))
МОТ #9	2021-07-12 13:38

MOT test number 3397823551		193
Result	✓ Pas	sed
Advice	Offside Front Fluid leak, but not excessive hub (8.4.1 (a) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))	
Advice	Offside Drag link end ball joint has slight play (2.1.3 (b) (i))	

MOT #8	2021-07-12 13:38	
MOT test number	802864832395	
Result	× Failed	
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Offside Drag link end ball joint has slight play (2.1.3 (b) (i))		
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))		
Pass with rectification	Offside Rear Position lamp adversely affected by the operation of another lamp	
(4.2.3 (c))		
Advice Offside Front Fluid leak, but not excessive hub (8.4.1 (a) (i))		





MOT #7	2020-03-12 10:27
MOT test number	502709195079
Result	✓ Passed
AdviceOffside Rear Brake disc worn, pitted or scored, but not seriously with MinorMinorOffside Steering linkage ball joint ball joint dust cover damaged or ingress of dirt steering drop arm (2.1.3 (g) (i))AdviceNearside Front Lower Anti-roll bar ball joint has slight play (5.3.4	deteriorated, but preventing the

MOT #6		2018-04-25 11:44
MOT test	number	975049519412
Result		✓ Passed
Advice	Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)	
Advice	Offside Front Ball joint has slight play steering drop arm (2.2.B.1f)	

МОТ #5	2018-04-24 09:31
MOT test number	284705086181
Result	🗙 Failed
Advice Offside Front Ball joint has slight play steering drop arm (2.2.B.1f)	
Fail Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)	
Fail Offside Ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt steering drop arm (2.2.C.1c)	
Fail Fuel system component leaking fuel filter (7.2.3)	

MOT #4	2017-03-03 06:56
MOT test number	971684276097
Result	✓ Passed
Advice Offside Rear brake can be felt dragging when rotated by hand, further investig recommended.	ation






МОТ #3	2017-03-01 12:51	
MOT test number	982895163122	
Result	🗙 Failed	
Fail Offside Drag link end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)		
Advice Offside Rear brake can be felt dragging when rotated by hand, further investigation recommended.		
MOT #2	2016-02-22 11:17	
MOT test number	898263525873	
Result	✓ Passed	
MOT #1	2015-03-06 15:19	
MOT test number	318035565046	
Result	✓ Passed	



Tax & MOT check







Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE C
Category	 Lamp
Туре	
Damage 2	AMPLE
Date	 4
Category	 AMPLI
Туре	W CON

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info	>
Plate changes		

Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2003-03-07
Last registration	2024-04-18
Complete history	See info



2003-03-07	20 mi
2015-03-06	51.724 mi
2016-02-22	53.289 mi
2017-03-01	59.194 mi
2017-03-03	59.196 mi
2018-04-24	62.748 mi
2018-04-25	62.749 mi
2020-03-12	63.319 mi
	11.777 mi
	11.777 esi
	11.777 mi
	11.777 esi
	11.777 mi
	11.777 esi
	11.777 mi
	11.777 est
	11.777 mi
	2015-03-06 2016-02-22 2017-03-01 2017-03-03 2018-04-24 2018-04-25

More info \rightarrow





Dimensions & weight

Width	1790 mm
Height	1968 mm
Length	3649 mm
Max. allowed weight	2400 kg
Additional information	

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of axles	2
Engine number	45P59658A