



report date: 2024-03-29

General information

Make	AUDI
Model	A6 TDI QUATTRO S LINE
Colour	Grey
Year of manufacture	2006
Top speed	138 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	177 BHP
Max. torque	379 Nm at 1.400 rpm
Engine capacity	2.696 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	41.5 mpg
Consumption combined	33.6 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-01-27
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-23
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	31
Total items failed	11

MOT #20 2024-01-19 15:57

MOT test number 794648484727

Result ✓ Passed

Next expiry date 2025-01-23

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Headlamp lens slightly defective both (4.1.1 (b) (i))

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front upper (5.3.4 (a) (i))

MOT #19 2023-01-24 12:28

MOT test number 607897863327

Result ✓ Passed

Advice Nearside Front Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))

Minor Front Headlamp lens slightly defective Both sides (4.1.1 (b) (i))

**MOT #18**

2022-01-24 15:18

MOT test number

420897748081

Result

✓ Passed

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #17

2020-11-24 17:13

MOT test number

268511126439

Result

✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #16** 2020-11-24 12:46**MOT test number** 634304743367**Result** ✗ Failed**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #15** 2019-11-27 13:01**MOT test number** 640874064564**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14** 2018-11-22 12:12**MOT test number** 436399320085**Result** ✓ Passed**MOT #13** 2017-11-30 10:03**MOT test number** 604819438524**Result** ✓ Passed

**MOT #12** 2016-12-02 17:35**MOT test number** 644474690004**Result** ✓ Passed**MOT #11** 2016-12-02 09:32**MOT test number** 122320635028**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #10** 2015-12-03 15:12**MOT test number** 686416454738**Result** ✓ Passed**MOT #9** 2014-11-10 15:49**MOT test number** 195014614322**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front brake discs worn**MOT #8** 2013-12-09 12:42**MOT test number** 199633143368**Result** ✓ Passed**MOT #7** 2012-08-02 12:29**MOT test number** 638775712286**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2012-08-02 12:29**MOT test number** 675985612272**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-08-19 09:50**MOT test number** 319971531472**Result** ✓ Passed**Notice** Nearside rear tyre outer sidewall damaged close to limit**MOT #4** 2010-07-02 15:43**MOT test number** 234423580472**Result** ✓ Passed**Notice** Nearside rear tyre cut in outer sidewall**MOT #3** 2010-07-02 15:43**MOT test number** 274433880148**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Nearside rear tyre cut in outer sidewall**MOT #2** 2009-04-06 16:42**MOT test number** 642836999019**Result** ✓ Passed



MOT #1	2009-04-06 09:35
MOT test number	404836599017
Result	✗ Failed
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
23 January 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-01
Last registration	2024-01-19
Complete history	See info



Registration #1	2006-03-01	23 mi
Registration #2	2009-04-06	30.674 mi
Registration #3	2009-04-06	30.674 mi
Registration #4	2010-07-02	45.296 mi
Registration #5	2011-08-19	55.755 mi
Registration #6	2012-08-02	64.706 mi
Registration #7	2013-12-09	75.802 mi
Registration #8	2014-11-10	83.415 mi
Registration #9	2015-12-03	90.221 mi
Registration #10	2016-12-02	98.318 mi
Registration #11	2019-05-29	101.277 mi
Registration #12	2019-05-29	101.277 mi
Registration #13	2019-05-29	101.277 mi
Registration #14	2019-05-29	101.277 mi
Registration #15	2019-05-29	101.277 mi
Registration #16	2019-05-29	101.277 mi
Registration #17	2019-05-29	101.277 mi
Registration #18	2019-05-29	101.277 mi
Registration #19	2019-05-29	101.277 mi
Registration #20	2019-05-29	101.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1463 mm
Length	4933 mm
Wheel base	2759 mm
Kerb weight	1815 kg
Max. allowed weight	2445 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BPP 043458