





General information

Make	ΤΟΥΟΤΑ
Model	HILUX INVINCIBLE 4X4 D-4D DCB
Colour	Grey
Year of manufacture	2012
Top speed	109 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	169 BHP
Max. torque	360 Nm at 1.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.1 mpg
Consumption extra urban	38.7 mpg
Consumption combined	31.7 mpg





Internet history

Entry 1

Date

2021-10-19

Pictures

Listing price

View report

6



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-21
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	14
Total items failed	12

MOT #13	2023-09-22 11:21
MOT test number	979505894648
Result	✓ Passed
Next expiry date	2024-09-21

MOT #12	2022-08-30	0 17:24
MOT test	t number 7162868	366352
Result	✓ ✓	Passed
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #11	2022-08-30 17:24	
MOT test number	913399068446	
Result	× Failed	
Pass with rectification	Front Service brake excessively fluctuating (1.2.1 (e))	
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Pass with rectification	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Pass with rectification	Front Position lamp not working both (4.2.1 (a) (ii))	





MOT #10	2021-06-28 09:37
MOT test	number 949059976772
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material all rear compensator (1.1.11 (c))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9		2020-07-09 11:46
MOT test I	number	331232278362
Result		✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other materia	al compensator (1.1.11 (c))

MOT #8	2019-07-03 12:56
MOT test number	453377714306
Result	✓ Passed
Advice Brake pipe corroded, covered in grease or other material Various co	prroding. (1.1.11 (c))

MOT #7	2019-06-20 08:26
MOT test number	522203019857
Result	🗙 Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Electronic stability control warning lamp indicates a fault (7.12 (e))	
Advice Brake pipe corroded, covered in grease or other material Various corroding.	(1.1.11 (c))
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Stop lamp(s) all not working (4.3.1 (a) (iii))	





MOT #6	2018-07-02 12:49
MOT test number	418895315398
Result	✓ Passed
MOT #5	2017-06-07 12:15
MOT test number	724138542132

MOT #4	2017-06-02 12:59
MOT test number	355487624721
Result	🗙 Failed
Fail Nearside Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Offside Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #3	2016-06-14 15:04
MOT test number	768406492408
Result	✓ Passed

MOT test number 776296055113 Result ✓ Passed Notice Advise on rear drums slight mishaped in brake roller tester	MOT #2		2015-06-05 10:33
	MOT test	number	776296055113
Notice Advise on rear drums slight mishaped in brake roller tester	Result		✓ Passed
Advice Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)			





MOT #1	2015-05-26 10:32
MOT test number	439256445187
Result	🗙 Failed
Fail Windscreen has damage to the swept area in excess of a 40mm circle outside	de zone 'A' (8.3.1d)
Notice Advise on rear drums slight mishaped in brake roller tester	
Advice Offside Front Seat belt damaged but webbing not significantly weakened	l (5.2.2a)



YP12MWU report date: 2024-03-29

Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 June 2024	Expires: 21 September 2024
Tax status	Valid until 1 June
Days left	33
MOT expiry date	21 September 2024
Full MOT history	See MOT history





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-14
Last registration	2023-09-22
Complete history	<u>See info</u>



Registration #1	2012-06-14	7 mi
Registration #2	2015-05-26	24.099 mi
Registration #3	2015-06-05	24.404 mi
Registration #4	2016-06-14	35.061 mi
Registration #5	2017-06-02	43.667 mi
Registration #6	2017-06-07	43.687 mi
Registration #7	2018-07-02	50.712 mi
Registration #8	2019-06-20	56.615 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 mi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi





Car features

S0225	Air conditionin
\$0295	
\$0482	
\$0501	
50566	
50567	
50569	

Dimensions & weight

Width	1835 mm
Height	1810 mm
Length	5255 mm
Kerb weight	1970 kg
Max. allowed weight	3020 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1KD5620298