





General information

| Make | ΤΟΥΟΤΑ |
|---------------------|---------------------------|
| Model | VERSO VALVEMATIC T SPIRIT |
| Colour | Silver |
| Year of manufacture | 2009 |
| Top speed | 115 mph |
| 0 - 60 mph | 10.4 seconds |
| Gearbox | 7 speed Manual |

Engine & fuel consumption

| Power | 145 BHP |
|-------------------------|---------------------|
| Max. torque | 180 Nm at 4.000 rpm |
| Engine capacity | 1.798 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 164 g/km |
| CO2 label | G |







Internet history


Entry 1

Date Pictures 2021-06-24

Listing price

View report

31



source: autotrader.co.uk



MOT history

| MOT expiry date | 2023-12-02 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 29 |
| Total items failed | 14 |

| MOT #15 | 2022-12-03 17:03 |
|--|------------------|
| MOT test number | 225262459911 |
| Result | ✓ Passed |
| Next expiry date | 2023-12-02 |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |) |

| MOT #14 | | 2021-11-25 21:08 |
|----------|---|------------------|
| MOT test | number | 303287372065 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #13 | 2020-11-27 18:13 |
|---|------------------|
| MOT test number | 617518299413 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |



| EA | 09 | 0 | Μ | Ρ |
|------|--------|---------------|-------|------|
| repo | ort da | te: 20 |)24-0 | 3-28 |

| MOT #12 | 2020-11-25 10:59 | |
|---|------------------|--|
| MOT test number | 866802701390 | |
| Result | 🗙 Failed | |
| Fail Offside Front Obligatory mirror insecure (3.3 (b) (ii)) | | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | | |

| MOT #11 | | 2019-04-17 13:02 |
|----------|---|------------------|
| MOT test | number | 432719218698 |
| Result | | ✓ Passed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #10 | 2019-04-17 09:57 | |
|---|------------------|--|
| MOT test number | 159978821848 | |
| Result | 🗙 Failed | |
| Fail Rear Registration plate inscription illegible (0.1 (b)) | | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Fail Electronic stability control warning lamp indicates a fault (7.12 (e)) | | |
| Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) | | |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | | |
| Fail Nearside Rear Position lamp not working (4.2.1 (a)) | | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | | |



EA090MP report date: 2024-03-28

| МОТ #9 | | 2018-03-26 09:47 |
|---|--|------------------|
| MOT test number | | 100340974206 |
| Result | | ✓ Passed |
| Advice Rear registration | n plate deteriorated but not likely to be misread (6.3.1d) | |
| MOT #8 | | 2018-03-26 09:47 |
| MOT test number | | 370552592293 |
| Result | | 🗙 Failed |
| Pass with rectification | Nearside Rear position lamp(s) not working (1.1.A.3b) | |
| Pass with rectification | Nearside Registration plate lamp not working (1.1.C.1d) | |
| Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d) | | |

| MOT #7 | 2017-04-12 11:24 |
|-----------------|------------------|
| MOT test number | 565736911618 |
| Result | ✓ Passed |

| МОТ #6 | 2016-04-12 10:52 |
|--|------------------|
| MOT test number | 738041359985 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to the legal limit Inner Edge (4.1.E.1) | |

| MOT #5 | | 2015-04-09 15:52 |
|----------|--|------------------|
| MOT test | number | 497739195066 |
| Result | | ✓ Passed |
| Notice | Child seat fitted not allowing full inspection of adult belt | |
| Notice | Under-trays fitted obscuring some underside components | |



| MOT #4 | | 2014-04-10 14:43 |
|--------------------------------------|---|------------------|
| MOT test | number | 957620704132 |
| Result | | ✓ Passed |
| Notice | Child seat fitted not allowing full inspection of adult belt | |
| Advice | Rear registration plate delaminated but not likely to be misread (6.3.1d) | |
| Advice | Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.2 | li) |
| Advice | Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5 | 5.1i) |
| MOT #3 | | 2014-04-10 11:27 |
| MOT test | number | 625980604161 |
| | | |
| Result | | 🗙 Failed |
| | th rectification Nearside Headlamp aim too low (1.8) | 🗙 Failed |
| | th rectification Nearside Headlamp aim too low (1.8) Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.3 | |
| Pass with Advice | | |
| Pass with Advice | Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5. | |
| Pass with Advice | Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.3 ront registration plate deteriorated (6.3.1d) | |
| Pass withAdviceFailFailO | Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.3 ront registration plate deteriorated (6.3.1d) Iffside Windscreen wiper does not clear the windscreen effectively (8.2.2) | 1i) |
| Pass withAdviceFailFailOAdviceAdvice | Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.3 ront registration plate deteriorated (6.3.1d) Iffside Windscreen wiper does not clear the windscreen effectively (8.2.2) Nearside Front Brake pad(s) wearing thin (3.5.1g) | 1i) |

Notice Child seat fitted not allowing full inspection of adult belt

Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)



EA090MP report date: 2024-03-28

| MOT #2 | | 2013-03-21 16:24 |
|--------------------------|---|------------------|
| MOT test number | | 966860483051 |
| Result | | ✓ Passed |
| Advice Offside Front Tyr | e worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Front T | yre worn close to the legal limit (4.1.E.1) | |
| Advice Offside Rear Tyre | e worn close to the legal limit (4.1.E.1) | |
| MOT #1 | | 2012-03-09 16:19 |
| MOT test number | | 709849062005 |

| Result | ✓ Passed | |
|--------|------------------------------|------------------------------------|
| Notice | Front discs slightly lipped | |
| Notice | Minor scratches on front lip | |
| | | Notice Front discs slightly lipped |



Tax & MOT check

| √ Taxed | × мот |
|-------------------------|-----------------------------|
| Tax due: 1 July 2024 | Expired: 2 December 2023 |
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 2 December 2023 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| - |
|-----|
| AMP |
| |
| |
| - A |
| |
| |
| |
| |

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|---|-------------|
| *********** | |
| ******* | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this TOYOTA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |



EA090MP report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2009-05-16 |
| Last registration | 2022-12-03 |
| Complete history | See info |



| Registration #1 | 2009-05-16 | 19 mi |
|------------------|------------|------------|
| Registration #2 | 2012-03-09 | 27.486 mi |
| Registration #3 | 2013-03-21 | 45.316 mi |
| Registration #4 | 2014-04-10 | 55.349 mi |
| Registration #5 | 2014-04-10 | 55.349 mi |
| Registration #6 | 2015-04-09 | 64.332 mi |
| Registration #7 | 2016-04-12 | 72.189 mi |
| Registration #8 | 2017-04-12 | 81.428 mi |
| Registration #9 | 2018-03-26 | 90.934 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 esi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 esi |
| | | |
| Registration #16 | | 11.777 est |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

Number of axles

NCAP rating

Video

see crash video



| Dimensions & weight | |
|------------------------|-----------------------|
| Width | 1790 mm |
| Height | 1630 mm |
| Length | 4440 mm |
| Wheel base | 2780 mm |
| Kerb weight | 1525 kg |
| Max. allowed weight | 2125 kg |
| Additional information | |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 7 |

2