



report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE V8 R
Colour	Black
Year of manufacture	2004
Top speed	155 mph
0 - 60 mph	5.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	400 BHP
Max. torque	552 Nm at 3.500 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.3 mpg
Consumption extra urban	30.4 mpg
Consumption combined	22.4 mpg
CO2 emission	314 g/km
CO2 label	M






Internet history

Entry 1

Date	2021-12-04
Pictures	7
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-01-17
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	58
Total items failed	2

MOT #21	2024-01-18 12:51
MOT test number	532837412843
Result	✓ Passed
Next expiry date	2025-01-17
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #20	2024-01-11 10:41
MOT test number	470424691933
Result	✗ Failed
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sills (5.3.6 (a) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #19	2022-11-23 12:29
MOT test number	329263074945
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin Foot and handbrake pads (1.1.13 (a) (ii))
Advice	Exhaust noisy (8.1.1 (a))

**MOT #18** 2021-10-21 15:07**MOT test number** 215637350673**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Sill trims fitted
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17** 2021-10-13 13:40**MOT test number** 113897045428**Result** ✗ Failed

- MAJOR** Nearside Rear Lower Suspension arm ball joint excessively worn rose type (5.3.4 (a) (i))
- MAJOR** Nearside Front Lower Shock absorbers has an excessively worn bush as chalked (5.3.2 (c))
- MAJOR** Nearside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Offside Rear Upper Suspension component pin or bush excessively worn tie rod arm (5.3.4 (a) (i))
- Advice** Sill trims fitted
- MAJOR** Offside Rear Lower Suspension arm ball joint excessively worn rose type (5.3.4 (a) (i))
- MAJOR** Offside Rear Lower Shock absorbers has an excessively worn bush as chalked (5.3.2 (c))
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Rear Upper Suspension component pin or bush excessively worn tie rod arm (5.3.4 (a) (i))

**MOT #16**

2020-09-29 15:55

**MOT test number**

786256018533

**Result**

✓ Passed

- Advice** Offside Rear sub frame bush slightly worn
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2019-10-07 17:11

**MOT test number**

434942048921

**Result**

✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm shock absorber lower mounting bush (5.3.4 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14**

2019-10-07 10:26

**MOT test number**

179749751420

**Result**

✗ Failed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm shock absorber lower mounting bush (5.3.4 (a) (i))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick parking brake (1.1.13 (a) (ii))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn arm shock absorber lower mounting bush (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13** 2018-10-08 14:29**MOT test number** 374558495642**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive rear diff (8.4.1 (a) (i))

**MOT #12** 2018-10-08 14:29**MOT test number** 746529055276**Result** ✗ Failed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Oil leak, but not excessive rear diff (8.4.1 (a) (i))

**MOT #11** 2017-09-27 10:20**MOT test number** 252302675336**Result** ✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)
- Advice** Nearside and offside rear tracking arm ball joint - inner and outer - dustcovers deteriorated
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #10** 2016-09-28 15:01**MOT test number** 106757446392**Result** ✓ Passed

- Advice** Coolant leak

**MOT #9** 2015-03-09 13:11**MOT test number** 175968465003**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2014-01-22 11:51**MOT test number** 505742424085**Result** ✓ Passed**MOT #7** 2014-01-16 11:53**MOT test number** 186636414410**Result** ✗ Failed**Fail** Inner Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2012-10-26 11:10**MOT test number** 106670102393**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Tested wet**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-10-14 10:53**MOT test number** 376657481212**Result** ✓ Passed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Wiper blades starting to split**Notice** SLIGHT REAR BRAKE IMBALANCE**Notice** Front brake imbalance 22%



MOT #4	2010-10-22 12:10
MOT test number	754065890266
Result	✓ Passed
MOT #3	2009-10-21 10:51
MOT test number	302064899227
Result	✓ Passed
MOT #2	2008-10-17 11:07
MOT test number	734531598272
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #1	2007-10-04 11:35
MOT test number	274807877226
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
17 January 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	17 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-10-21
Last registration	2024-01-18
Complete history	<a href="#">See info</a>



Registration #1	2004-10-21	22 mi
Registration #2	2007-10-04	33.980 mi
Registration #3	2008-10-17	38.620 mi
Registration #4	2009-10-21	45.973 mi
Registration #5	2010-10-22	49.393 mi
Registration #6	2011-10-14	55.310 mi
Registration #7	2012-10-26	61.455 mi
Registration #8	2014-01-16	65.902 mi
Registration #9	2014-01-22	65.915 mi
Registration #10	2015-03-09	70.856 mi
Registration #11	2016-09-28	76.243 mi
Registration #12	2017-09-27	84.063 mi
Registration #13	2018-05-20	91.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2020-05-20	99.277 mi
Registration #16	2021-05-20	103.277 mi
Registration #17	2022-05-20	107.277 mi
Registration #18	2023-05-20	111.277 mi
Registration #19	2024-01-18	115.277 mi
Registration #20		
Registration #21		
Registration #22		
Registration #23		

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1800 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	1B0305170011