





General information

Make	PEUGEOT
Model	107 ACCESS
Colour	Silver
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А







Internet history

Entry 1

Date Pictures 2021-10-01

8

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-13
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	10
Total items failed	7

MOT #12	2	024-02-14 15:04
MOT test	number	687309245778
Result		🗸 Passed
Next expi	iry date	2025-02-13
Advice	Nearside Front Tyre worn close to legal limit/worn on edge replace as soon as possi	ble (5.2.3 (e))
Advice Offside Rear Tyre worn close to legal limit/worn on edge replace as soon as possible (5.2.3 (e))		e (5.2.3 (e))
Advice	Vice Offside Front Tyre worn close to legal limit/worn on edge replace as soon as possible (5.2.3 (e))	

MOT #11 2024-02-14 15:04 MOT test number 641946308009 Result × Failed Advice Nearside Front Tyre worn close to legal limit/worn on edge replace as soon as possible (5.2.3 (e)) Advice Offside Rear Tyre worn close to legal limit/worn on edge replace as soon as possible (5.2.3 (e)) Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge replace as soon as possible (5.2.3 (e))



KN12LBX report date: 2024-03-29

MOT #10		2022-11-21 15:24
MOT test	number	889052772390
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #9		2022-11-21 10:33
MOT test	number	721134258285
Result		🗙 Failed
Fail Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))		
Fail S	upplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
Fail V	Vindscreen seriously discoloured and affecting the driver's view of the road (3.2 (a)	(ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #8	2021-10-20 11:00
MOT test number	347856239692
Result	✓ Passed
MOT #7	2020-10-07 10:16
MOT test number	659246165471
Result	✓ Passed
MOT #6	2019-10-11 12:04

	2013-10-11-12.04
MOT test number	482447984365
Result	✓ Passed





MOT #5	2018-10-11 11:21	
MOT test number	818076262468	
Result	✓ Passed	
NOT #4	2017 00 14 14 40	
MOT #4	2017-09-14 14:46	
MOT test number	903485566815	
Result	✓ Passed	
MOT #3	2017-09-14 11:49	
MOT test number	831636711327	
Result	🗙 Failed	
Fail Offside Front Body has a projection caused by damage front bumper insecure (6.1.C.1)		
Fail Windscreen washer provides insufficient washer liquid (8.2.3)		
MOT #2	2016-08-16 09:41	
MOT test number	103896081244	

MOT test number	103896081244
Result	✓ Passed
MOT #1	2015-02-21 09:27
MOT test number	307482155012

Result

🗸 Passed



Tax & MOT check

	✓ Taxed		✓ МОТ
Tax due: 1 April 2025		Expires: 13 February 2025	
Tax status			Valid until 1 April
Days left			337
MOT expiry date			13 February 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		48	

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



KN12LBX report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-16
Last registration	2024-02-14
Complete history	See info



Registration #1	2012-03-16	22 mi
Registration #2	2015-02-21	17.647 mi
Registration #3	2016-08-16	21.921 mi
Registration #4	2017-09-14	27.286 mi
Registration #5	2017-09-14	27.286 mi
Registration #6	2018-10-11	31.477 mi
Registration #7	2019-10-11	33.857 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.227 mi
Registration #14		00.000 and



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings		
NCAP rating	****	
Video	see crash video	
Dimensions & weight		
Width		1630 mm
Height		1465 mm
Length		3430 mm
Wheel base		2340 mm
Kerb weight		900 kg
Max. allowed weight		1180 kg
Additional information		
Fuel tank capacity		35 I
Fuel delivery		Multi-Point Injection
Number of doors		3
Number of seats		4
Number of axles		2
Engine number		7155098