



General information

Make	FORD
Model	KUGA GHIA TDCI
Colour	Blue
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-25
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2023-05-27
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	18
Total items failed	16

MOT #15	2022-05-26 07:42
MOT test number	220157055472
Result	✓ Passed
Next expiry date	2023-05-27
Advice	Offside Front Brake pedal wearing smooth (1.1.2 (c))
Advice	Nearside Rear Nail in tyre
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #14**

2022-05-25 08:45

**MOT test number**

903518160496

**Result****✗ Failed**

- Fail** Front Windscreen washer not working (3.5 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Brake pedal wearing smooth (1.1.2 (c))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Offside Front Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))
- Advice** Nearside Rear Nail in tyre
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #13**

2021-05-28 13:17

**MOT test number**

633379708857

**Result****✓ Passed**

**MOT #12** 2020-08-11 08:38**MOT test number** 157175872102**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2019-08-08 08:28**MOT test number** 518587076388**Result** ✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2018-08-01 13:55**MOT test number** 113828691081**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2017-08-12 09:06**MOT test number** 923272529676**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2017-08-12 08:32**MOT test number** 754932065915**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Steering rack gaiter insecure (2.2.D.2d)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2016-10-04 13:27**MOT test number** 852298053923**Result** ✓ Passed**MOT #6** 2015-10-15 14:27**MOT test number** 132516755856**Result** ✓ Passed**MOT #5** 2015-10-15 14:27**MOT test number** 564574025471**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp has less than 50% of the light sources illuminating (1.2.1b)**MOT #4** 2014-10-08 08:49**MOT test number** 775001684284**Result** ✓ Passed**MOT #3** 2013-10-23 14:57**MOT test number** 319566793496**Result** ✓ Passed



MOT #2	2013-10-23 14:57
MOT test number	405736993233
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Pass with rectification	Offside Headlamp aim too low (1.8)

MOT #1	2012-10-24 08:43
MOT test number	505548092295
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
31 March 2023

X

MOT

Expired:  
27 May 2023

Tax status	Expired at 31 March 2023
Days left	394 days too late
MOT expiry date	27 May 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-30
Last registration	2022-05-26
Complete history	<a href="#">See info</a>



Registration #1	2009-10-30	13 mi
Registration #2	2012-10-24	23.770 mi
Registration #3	2013-10-23	34.789 mi
Registration #4	2014-10-08	45.117 mi
Registration #5	2015-10-15	56.740 mi
Registration #6	2015-10-15	56.740 mi
Registration #7	2016-10-04	67.958 mi
Registration #8	2017-08-12	78.176 mi
Registration #9	2018-05-22	88.394 mi
Registration #10	2019-05-22	98.612 mi
Registration #11	2020-05-22	108.830 mi
Registration #12	2021-05-22	119.048 mi
Registration #13	2022-05-26	129.266 mi
Registration #14	2023-05-26	139.484 mi
Registration #15	2024-03-28	149.702 mi
Registration #16	2024-03-28	159.920 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9K79192