





report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE TEKNA DIG-T XTRONIC
Colour	Silver
Year of manufacture	2016
Top speed	115 mph
0 - 60 mph	12.7 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	115 BHP
Max. torque	165 Nm at 1.750 rpm
Engine capacity	1.198 сс
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date	2021-11-02	
Pictures	0	
Listing price	View report	

source: heycar.co.uk

Entry 1

,	2021 11 01	
Date	2021-11-01	
Pictures	26	
Listing price	<u>View report</u>	









source: cargurus.co.uk

CarCheck.co.uk page 2/11



LR66GYN report date: 2024-03-28

MOT history

MOT expiry date	2024-10-01
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #6		2023-10-02 15:05
MOT test	number	476025054753
Result		✓ Passed
Next expi	ry date	2024-10-01
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5		2022-09-08 13:43
MOT test	number	310797877953
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing tread groves (5.2.3 (d) (ii))		
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing tread groves (5.2.3	(d) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2022-09-08 13:43 **MOT test number** 467762287690 Result × Failed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tread groves (5.2.3 (d) (ii)) Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Tyre slightly damaged/cracking or perishing tread groves (5.2.3 (d) (ii)) Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

MOT #3	2021-09-06 14:31
MOT test number	961344923306
Result	✓ Passed
MOT #2	2020-09-11 10:42
MOT test number	203849995922
Result	✓ Passed
MOT #1	2019-09-06 11:45
MOT test number	190101776675
Result	✓ Passed

CarCheck.co.uk page 4/11



LR66GYN report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	1 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

\sim		h:a	+
- CJV	vner	mis	\mathbf{I}

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
HARMAN CONTRACTOR CONT	
THE STREET STREE	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	ZIN UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-14
Last registration	2023-10-02
Complete history	See info



Registration #1	2016-09-14	24 mi
Registration #2	2019-09-06	24.794 mi
Registration #3	2020-09-11	29.211 mi
Registration #4	2021-09-06	34.285 mi
Registration #5		9.777 es
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	81%
Pedestrian	75%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1768 mm
Height	1520 mm
Length	4387 mm
Wheel base	2700 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	46 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number 254452A