





report date: 2024-03-29

General information

| Make | FORD |
|---------------------|-----------------------------------|
| Model | TRANSIT CONNECT T200 TREND LR P/V |
| Colour | White |
| Year of manufacture | - |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 90 BHP |
|-------------|---------------------|
| Max. torque | 240 Nm at 1.750 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-07

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

| MOT #11 | 2023-07-20 16:28 |
|---|------------------|
| MOT test number | 264781263698 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-19 |
| Advice Nearside Front tyre wearing on edges | |
| Advice Oil leak from engine | |
| Advice Offside Front tyre wearing on inner edge | |

| MOT #10 | | 2022-07-05 14:54 |
|----------|---|------------------|
| MOT test | number | 749366179310 |
| Result | | ✓ Passed |
| Advice | Water leak from bottom hose | |
| Advice | Nearside Front tyre worn on inner edge | |
| Advice | Oil leak from engine | |
| Advice | Rear brake discs corroded due to standing | |

| MOT #9 | 2021-07-15 15:43 |
|---|------------------|
| MOT test number | 151067271639 |
| Result | ✓ Passed |
| Advice Offside Front tyre worn on inner edge | |
| Advice Nearside Front tyre worn on inner edge | |
| Advice Offside Front wiper broken | |
| Advice Oil leak from engine | |

| MOT #8 | 2020-07-09 08:39 |
|-----------------|------------------|
| MOT test number | 436159103309 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #7 2019-07-04 15:49

MOT test number 708534276152

MOT #6 2019-07-03 08:41

MOT test number 726570540367

Result X Failed

Fail Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

Fail Nearside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

Fail Offside Rear Position lamp not working (4.2.1 (a) (ii))

Fail Offside Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Fail Nearside Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Fail Offside Inner Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MOT #5 2018-07-19 09:24

MOT test number 782828979976

Result
✓ Passed

MOT #4 2017-07-18 10:07

MOT test number 922081508058

Result ✓ Passed

Advice Front Exhaust has a minor leak of exhaust gases flexi pipe (7.1.2)

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #3 2017-07-18 10:07

MOT test number 762945193660

Result X Failed

Pass with rectification Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Pass with rectification Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Front Exhaust has a minor leak of exhaust gases flexi pipe (7.1.2)

Pass with rectification Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #2 2016-07-12 11:04

MOT test number 953358664524

Result
✓ Passed

Advice Front Exhaust has a minor leak of exhaust gases flexable pipe (7.1.2)

MOT #1 2015-07-13 12:36

MOT test number 307144595192

Result \rightarrow Passed

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is | |
|--|-------------|
| | |
| HARMAN CONTRACTOR CONT | |
| | |
| *************************************** | |
| ******* | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | OK OK |
| Plate since | |
| Current registration | UK ZIS |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



MX10KVO report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



MX10KVO report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2010-08-01 |
| Last registration | 2023-07-20 |
| Complete history | See info |



| Registration #1 | 2010-08-01 | 28 mi |
|------------------|------------|------------|
| Registration #2 | 2015-07-13 | 108.175 mi |
| Registration #3 | 2016-07-12 | 116.763 mi |
| Registration #4 | 2017-07-18 | 127.119 mi |
| Registration #5 | 2017-07-18 | 127.119 mi |
| Registration #6 | 2018-07-19 | 133.562 mi |
| Registration #7 | 2019-07-03 | 146.348 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 mi |

More info >

CarCheck.co.uk page 10/11



MX10KVO report date: 2024-03-29

Car features

| 50225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Dimensions & weight

| Width | 1795 mm |
|---------------------|---------|
| Height | 1815 mm |
| Length | 4275 mm |
| Wheel base | 2664 mm |
| Kerb weight | 1399 kg |
| Max. allowed weight | 2040 kg |

Additional information

| Fuel tank capacity | 60 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of seats | 2 |
| Number of axles | 2 |
| Engine number | 9E51888 |

CarCheck.co.uk page 11/11