



RENAULT

YCI3LLE

report date: 2024-03-29

General information

|                     |                              |
|---------------------|------------------------------|
| Make                | RENAULT                      |
| Model               | TRAFIC LL29 STANDARD DCI 115 |
| Colour              | Black                        |
| Year of manufacture | 2013                         |
| Top speed           | 93 mph                       |
| Gearbox             | 6 speed Manual               |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 115 BHP             |
| Max. torque             | 300 Nm at 1.500 rpm |
| Engine capacity         | 1.995 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 32.8 mpg            |
| Consumption extra urban | 47.9 mpg            |
| Consumption combined    | 40.9 mpg            |
| CO2 emission            | 190 g/km            |
| CO2 label               | J                   |





## Internet history

### Entry 3

Date 2023-12-12

Pictures 8




source: g3remarketing.co.uk

### Entry 2

Date 2021-06-26

Pictures 34

Listing price [View report](#)




source: cargurus.co.uk

### Entry 1

Date 2021-06-25

Pictures 34

Listing price [View report](#)



source: autotrader.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-07-20 |
| MOT pass rate      | 50 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 9          |
| Total advice items | 17         |
| Total items failed | 30         |

MOT #18 2023-07-21 12:44

MOT test number 542381747968

Result ✓ Passed

Next expiry date 2024-07-20

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened n/s o/s (1.1.14 (a) (ii))

**Advice** Nearside Rear wheel chair locking runner is worn

**Advice** Offside Rear loading ramp spring is broken

**Advice** Hand brake just met its limit

MOT #17 2023-07-21 09:20

MOT test number 121997695148

Result ✗ Failed

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Nearside Rear wheel chair locking runner is worn

**Fail** Offside Rear Parking brake inoperative on one side poor effort (1.4.1 (a))

**Advice** Offside Rear loading ramp spring is broken

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened n/s o/s (1.1.14 (a) (ii))

**Fail** Engine MIL inoperative or indicates a malfunction engine light lit on the dash (8.2.2.2 (g))

**MOT #16**

2023-07-03 09:44

**MOT test number**

439405472732

**Result****✗ Failed**

- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Clutch is slipping badly
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords has a cut in its tread (5.2.3 (d) (i))
- Fail** Offside Rear Lower Suspension arm pin or bush excessively worn axle lower arm bush is split away arm fouling its fixing (5.3.4 (a) (i))
- Fail** Central Front Exhaust has a major leak of exhaust gases down pipe flexi (6.1.2 (a))
- Minor** Power steering fluid level below minimum (2.1.5 (b) (i))
- Fail** Emissions unable to be completed due to condition of exhaust (8.2.2.2 (e))
- Advice** Nearside Rear locking strap runner on the floor is worn
- Fail** Offside Rear Parking brake inoperative on one side very poor effort (1.4.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Rear Lower Suspension arm pin or bush excessively worn axle lower arm bush is split away arm fouling its fixing (5.3.4 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction engine light lit on the dash (8.2.2.2 (g))
- Advice** Offside Rear chair loading ramp spring is broken

**MOT #15**

2022-07-04 11:23

**MOT test number**

318775054602

**Result****✓ Passed**

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2022-06-23 07:29

**MOT test number**

680540155253

**Result****✗ Failed****Advice**

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail**

Offside Rear Brake pipe excessively corroded at hose union (1.1.11 (c))

**Fail**

Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail**

Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Fail**

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Fail**

Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #13**

2021-06-25 09:48

**MOT test number**

229066128406

**Result****✓ Passed****MOT #12**

2020-09-30 16:03

**MOT test number**

579771902092

**Result****✓ Passed****MOT #11**

2020-09-30 16:03

**MOT test number**

813359415023

**Result****✗ Failed****Pass with rectification**

Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

**MOT #10**

2020-09-07 16:02

**MOT test number**

646240578570

**Result****✗ Failed****Fail**

Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Fail**

Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail**

Central Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))

**Advice**

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Minor**

Hazard warning switch faulty (4.4.2 (a) (i))

**Fail**

Emissions not tested (8.2.2.2 (e))

**MOT #9**

2019-11-08 12:27

**MOT test number**

988522043544

**Result****✓ Passed****MOT #8**

2019-10-28 16:02

**MOT test number**

864388865554

**Result****✗ Failed****Fail**

Offside Rear Body component damaged and likely to cause injury light lense (6.2.1 (a) (i))

**MOT #7**

2018-12-06 13:54

**MOT test number**

548572799235

**Result****✓ Passed****MOT #6**

2018-12-05 15:17

**MOT test number**

364176456440

**Result****✗ Failed****Fail**

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #5** 2018-01-25 12:24**MOT test number** 237542009594**Result** ✓ Passed**MOT #4** 2018-01-25 12:24**MOT test number** 138062825487**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2017-03-08 09:38**MOT test number** 664306961256**Result** ✓ Passed**MOT #2** 2017-02-23 09:37**MOT test number** 952296472895**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Rear Rear fog lamp adversely affected by the operation of another lamp Reverse lights illuminate when fog light is on (1.3.2f)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Central Rear Upper Stop lamp not working (1.2.1b)**MOT #1** 2016-04-28 09:43**MOT test number** 212076187671**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
20 July 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 August            |
| <b>Days left</b>        | 93                              |
| <b>MOT expiry date</b>  | 20 July 2024                    |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | J          |
| <b>Single payment (12 months)</b>              | £ 365,00,- |
| <b>Single six month payment</b>                | £ 200,75,- |
| <b>Total payable by 12 monthly instalments</b> | £ 383,25,- |





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2019-01-01    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2019-01-01    |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

|                   |                 |
|-------------------|-----------------|
| Finance company   | RENAULT FINANCE |
| Date of agreement | 01/01/2024      |
| Agreement type    | FINANCE         |
| Agreement term    | 36 months       |
| Agreement number  | 123456789       |
| Contact info      | 0123 456789     |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 21                       |
| First mileage registration | 2013-07-15               |
| Last registration          | 2023-07-21               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2013-07-15 | 17 mi     |
| Registration #2  | 2016-04-28 | 32.757 mi |
| Registration #3  | 2017-02-23 | 42.645 mi |
| Registration #4  | 2017-03-08 | 42.645 mi |
| Registration #5  | 2018-01-25 | 55.766 mi |
| Registration #6  | 2018-01-25 | 55.766 mi |
| Registration #7  | 2018-12-05 | 69.666 mi |
| Registration #8  | 2018-12-06 | 69.666 mi |
| Registration #9  | 2019-10-28 | 80.818 mi |
| Registration #10 | 2019-11-08 | 80.842 mi |
| Registration #11 | 2020-09-07 | 92.763 mi |
| Registration #12 | 2020-09-07 | 92.763 mi |
| Registration #13 | 2020-09-07 | 92.763 mi |
| Registration #14 | 2020-09-07 | 92.763 mi |
| Registration #15 | 2020-09-07 | 92.763 mi |
| Registration #16 | 2020-09-07 | 92.763 mi |
| Registration #17 | 2020-09-07 | 92.763 mi |
| Registration #18 | 2020-09-07 | 92.763 mi |
| Registration #19 | 2020-09-07 | 92.763 mi |
| Registration #20 | 2020-09-07 | 92.763 mi |
| Registration #21 | 2020-09-07 | 92.763 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 58%                             |
| Children       | 79%                             |
| Pedestrian     | 28%                             |
| Safety systems | 14%                             |
| Overall rating | 51%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1904 mm |
| Height              | 1954 mm |
| Length              | 5182 mm |
| Kerb weight         | 1907 kg |
| Max. allowed weight | 3055 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 90 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 9                |
| Number of axles    | 2                |

**Engine number**

C111145