






report date: 2024-03-29

#### General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI
Colour	White
Year of manufacture	2017
Top speed	100 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

#### Entry 1

Date 2021-12-10

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



DY67MVN report date: 2024-03-29

MOT history

MOT expiry date	2024-11-11
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #6		2023-11-10 16:00
MOT test	number	116666643618
Result		✓ Passed
Next expi	ry date	2024-11-11
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))

MOT #5	2022-11-10 14:3	39
MOT test	number 89194321338	31
Result	✓ Passe	d
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both inner surfaces (1.1.14 (a) (ii))		)
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake lining(s) wearing thin both (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2021-11-12 08:41

**MOT test number** 551636370570

MOT #3 2021-07-29 18:04

MOT test number 841837566266

**Result** ✓ Passed

MOT #2 2020-09-23 14:30

**MOT test number** 982622615731

**Result** 
✓ Passed

Advice Front Brake pad(s) wearing thin nearside and offside (1.1.13 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14

(a) (ii))

**MOT #1** 2020-09-22 14:24

**MOT test number** 852277415571

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin nearside and offside (1.1.13 (a) (ii))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	11 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



DY67MVN report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.		
********		
***************************************		
*********		
************		
	More info >	
Plate changes		
See in this check if this VAUXHALL had different number plates.		
Number of plates		,
Current registration	NK NE	
Plate since		
Current registration	UK UK	
Plate since		

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-28
Last registration	2023-11-10
Complete history	See info



Registration #1	2017-09-28	15 mi
Registration #2	2020-09-22	52.330 mi
Registration #3	2020-09-23	52.332 mi
Registration #4	2021-07-29	69.965 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		0.777-44
3		

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Safety ratings

NCAP rating	<b>大大大</b> 大大
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



# Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Wheel base	3498 mm
Kerb weight	1750 kg
Max. allowed weight	3030 kg

## Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	R9M H4 - C093506LWZ

CarCheck.co.uk page 11/11