



report date: 2024-03-28

General information

| | |
|---------------------|------------------|
| Make | MAZDA |
| Model | cx-3 SE NAV PLUS |
| Colour | White |
| Year of manufacture | 2019 |
| Top speed | 119 mph |
| 0 - 60 mph | 9.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 119 BHP |
| Max. torque | 206 Nm at 2.800 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 141 g/km |
| CO2 label | F |





Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2022-05-21 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-05-18 |
| Pictures | 32 |
| Listing price | View report |



source: [cargurus.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-15 |
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 1 |

MOT #4 2024-02-01 09:00

MOT test number 572731384071

Result ✓ Passed

Next expiry date 2025-02-15

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded on inner side (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded on inner side (1.1.14 (a) (ii))

MOT #3 2023-01-30 17:08

MOT test number 957364147066

Result ✓ Passed

MOT #2 2023-01-30 09:38

MOT test number 840526985483

Result ✗ Failed

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



| | |
|-----------------|------------------|
| MOT #1 | 2022-02-11 09:11 |
| MOT test number | 944903888023 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 94 |
| MOT expiry date | 15 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | H |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | FJ68WMT |
| Plate since | 2019-09-28 |
| Current registration | FJ68WMT |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 7 |
| First mileage registration | 2019-02-16 |
| Last registration | 2024-02-01 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2019-02-16 | 27 mi |
| Registration #2 | 2022-02-11 | 19.977 mi |
| Registration #3 | 2023-05-20 | 20.277 mi |
| Registration #4 | 2023-05-20 | 20.277 mi |
| Registration #5 | 2023-05-20 | 20.277 mi |
| Registration #6 | 2023-05-20 | 20.277 mi |
| Registration #7 | 2023-05-20 | 20.277 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 85% |
| Children | 79% |
| Pedestrian | 84% |
| Safety systems | 64% |
| Overall rating | 79% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1765 mm |
| Height | 1535 mm |
| Length | 4275 mm |
| Wheel base | 2570 mm |
| Max. allowed weight | 1692 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 48 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | PE 50 207410 |