





General information

| Make | KIA |
|---------------------|----------------|
| Model | CARENS 2 ISG |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 115 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 133 BHP | |
|-------------------------|---------------------|--|
| Max. torque | 165 Nm at 4.850 rpm | |
| Engine capacity | 1.591 cc | |
| Cylinders | 4 | |
| Fuel type | Petrol | |
| Consumption city | 36.2 mpg | |
| Consumption extra urban | 54.3 mpg | |
| Consumption combined | 45.6 mpg | |
| CO2 emission | 143 g/km | |
| CO2 label | F | |








Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-09-07 |
| Pictures | 19 |
| Listing price | View report |









source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-08-17 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 3 |
| Failed MOT tests | 2 |
| Total advice items | 10 |
| Total items failed | 3 |

| MOT #5 | 2023-08-16 13:46 |
|---|------------------|
| MOT test number | 256231546925 |
| Result | 🗸 Passed |
| Next expiry date 2024-08 | |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |

| МОТ #4 | 2023-08-16 09:39 |
|--|------------------|
| MOT test number | 546311428059 |
| Result | 🗙 Failed |
| Fail Nearside Rear Service brake excessively binding (1.2.1 (f)) | |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii) |) |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice Offside Rear Service brake binding but not excessively (1.2.1 (f)) | |

| MOT #3 | | 2022-08-18 08:33 |
|----------------|--|------------------|
| MOT test numbe | ۶r | 357863670654 |
| Result | | ✓ Passed |
| Advice TPMS | light on. | |
| Advice Offsid | de Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |





| MOT #2 | | 2021-08-05 15:52 |
|--|---|------------------|
| MOT test | number | 427038616294 |
| Result | | ✓ Passed |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) | | |
| Advice | Advice Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) | |
| | | |

| MOT #1 | 2021-08-05 15:52 | |
|---|---|--|
| MOT test number | 373769997031 | |
| Result | × Failed | |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) | | |
| Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) | | |
| (ii)) Advice Front Brake disc | worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) | |



report date: 2024-03-29

Tax & MOT check

| √ Taxed | √ MOT | |
|-------------------------------------|----------------------------|--|
| Tax due: 1 September 2024 | Expires: 17 August 2024 | |
| Tax status | Valid until 1 September | |
| Days left | 124 | |
| MOT expiry date | 17 August 2024 | |
| Full MOT history | See MOT history | |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|--|-------|
| Date | F | |
| Category | | ARME |
| Туре | | |
| Damage 2 | | AMPLE |
| | E E | |
| Date | | \$ |
| Category | AMP | |
| Туре | No. Contraction of the second se | |

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******** | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | 7 |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-09-24 |
| Last registration | 2023-08-16 |
| Complete history | See info |



| Registration #1 | 2018-09-24 | 10 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-08-05 | 17.720 mi |
| Registration #3 | 2021-08-05 | 17.720 mi |
| Registration #4 | | 11.777 esi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 94% |
| Children | 76% |
| Pedestrian | 64% |
| Safety systems | 81% |
| Overall rating | 83% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1805 mm |
| Height | 1605 mm |
| Length | 4525 mm |
| Wheel base | 2750 mm |
| Kerb weight | 1606 kg |
| Max. allowed weight | 2140 kg |
| Additional information | |
| Fuel tank capacity | 58 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 11/11 |