



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Silver
Year of manufacture	2010
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2024-07-20
MOT pass rate	55 %
MOT passed	11
Failed MOT tests	9
Total advice items	34
Total items failed	23

MOT #20	2023-07-21 13:20
MOT test number	385270068830
Result	✓ Passed
Next expiry date	2024-07-20
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive From oil Filter area (8.4.1 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Service brake binding but not excessively (1.2.1 (f))

**MOT #19**

2023-07-21 09:43

MOT test number

799828497250

Result**✗ Failed**

Fail Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen Washer fluid spraying in wrong direction from under bonnet (Split pipe) (3.5 (a))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Brake pipe excessively corroded To flexi - Brake pipe end/union heavily corroded. (1.1.11 (c))

Advice Oil leak, but not excessive From oil Filter area (8.4.1 (a) (i))

Fail Nearside Front Headlamp aim too low (4.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Service brake binding but not excessively (1.2.1 (f))

MOT #18

2022-07-14 15:06

MOT test number

926431747005

Result**✓ Passed**

Advice Rear Coil spring corroded Both rear (5.3.1 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))

MOT #17

2022-07-14 15:06

MOT test number

459626962058

Result**✗ Failed**

Advice Front Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))

Advice Rear Coil spring corroded Both rear (5.3.1 (b) (i))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #16**

2021-07-09 15:25

MOT test number

539791176639

Result

✓ Passed

Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Rear Coil spring corroded both (5.3.1 (b) (i))

MOT #15

2021-07-06 14:40

MOT test number

717442874543

Result

✗ Failed

Advice

Rear Coil spring corroded both (5.3.1 (b) (i))

Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail

Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail

Nearside Front Direction indicator not working (4.4.1 (a) (ii))

Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #14

2020-07-08 13:59

MOT test number

664130613361

Result

✓ Passed

MOT #13

2020-07-08 08:04

MOT test number

459609551503

Result

✗ Failed

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #12** 2019-04-09 11:58**MOT test number** 250023643481**Result** ✓ Passed**MOT #11** 2019-04-09 07:59**MOT test number** 353725589810**Result** ✗ Failed

- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MOT #10 2018-04-24 10:50**MOT test number** 865644787522**Result** ✓ Passed**MOT #9** 2018-04-24 07:58**MOT test number** 311427511559**Result** ✗ Failed

- Fail** Offside Front coil spring broken (2.4.C.1a)
- Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #8** 2017-04-26 15:47**MOT test number** 561394013077**Result** ✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Under trays fitted
- Advice** Power steering pipe(s) or hose(s) slightly corroded main high pressure pipe (2.3.2)

MOT #7 2017-04-26 07:47**MOT test number** 633005523638**Result** ✗ Failed

- Advice** Power steering pipe(s) or hose(s) slightly corroded main high pressure pipe (2.3.2)
- Advice** Under trays fitted
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Stop lamp not working (1.2.1b)

MOT #6 2016-04-08 07:39**MOT test number** 209902864660**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Under trays fitted
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-04-14 15:36**MOT test number** 336204305152**Result** ✓ Passed**Notice** Exhaust front flexi section leaking**MOT #4** 2015-04-14 11:58**MOT test number** 457474405145**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** Exhaust front flexi section leaking**MOT #3** 2014-04-25 12:47**MOT test number** 207825614162**Result** ✓ Passed**Notice** N/s/f wishbone rear bush split and deteriorating**MOT #2** 2013-04-19 14:05**MOT test number** 245059003150**Result** ✓ Passed**Notice** N/s/f wishbone rear bush starting to split**Notice** N/s/f tyre getting worn on outer edge**MOT #1** 2013-04-19 14:05**MOT test number** 157219003118**Result** ✗ Failed**Notice** N/s/f wishbone rear bush starting to split**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Notice** N/s/f tyre getting worn on outer edge



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
20 July 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	<div><div></div><div>*****</div></div>
Plate since	2019-06-29
Current registration	<div><div></div><div>*****</div></div>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-04-27
Last registration	2023-07-21
Complete history	See info



Registration #1	2010-04-27	26 mi
Registration #2	2013-04-19	14.121 mi
Registration #3	2014-04-25	24.888 mi
Registration #4	2015-04-14	33.235 mi
Registration #5	2015-04-14	33.235 mi
Registration #6	2016-04-08	41.068 mi
Registration #7	2017-04-26	49.714 mi
Registration #8	2017-04-26	49.714 mi
Registration #9	2018-04-24	53.186 mi
Registration #10	2018-04-24	53.186 mi
Registration #11	2019-04-22	55.277 mi
Registration #12	2019-04-22	55.277 mi
Registration #13	2020-04-20	55.277 mi
Registration #14	2020-04-20	55.277 mi
Registration #15	2021-04-18	55.277 mi
Registration #16	2021-04-18	55.277 mi
Registration #17	2022-04-16	55.277 mi
Registration #18	2022-04-16	55.277 mi
Registration #19	2023-04-14	55.277 mi
Registration #20	2023-04-14	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 058721