





report date: 2024-03-28

### General information

Make	MINI
Model	MINI JOHN COOPER WORKS
Colour	Black
Year of manufacture	2013
Top speed	139 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	215 BHP
Max. torque	280 Nm at 1.900 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/12



HK620L0

report date: 2024-03-28

### Internet history

#### Entry 3

Date 2021-09-29

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 2

Date 2021-09-27

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1


Date 2021-09-12

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-23
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	5
Total items failed	3

MOT #13	2023-10-24 13:42
MOT test number	336661446395
Result	<b>✓</b> Passed
Next expiry date	2024-10-23
Advice Front Oil leak from bottom	

MOT #12	2023-10-23 14:44
MOT test number	842294325823
Result	<b>X</b> Failed
Advice Nearside Rear Registration plate lamp in-operative	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Front Oil leak from bottom	

MOT #11	2022-10-13 15:30
MOT test number	813756641069
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #10	2021-10-13 14:11
MOT test number	736703170671
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



HK620LO

report date: 2024-03-28

 MOT #9
 2021-07-26 14:24

 MOT test number
 586865065111

 Result
 ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2020-07-16 12:51
MOT test number 655413912749

**Result** ✓ Passed

MOT #7 2019-10-29 16:43

**MOT test number** 749881580046

**Result** ✓ Passed

MOT #6 2019-10-29 11:46

**MOT test number** 266301875077

**Result** X Failed

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords side wall (5.2.3 (d) (i))

MOT #5 2018-10-29 13:26
MOT test number 819057893738

**Result** 
✓ Passed

MOT #4 2017-10-31 17:08

MOT test number 770670248629

MOT #3 2017-01-27 14:00

**MOT test number** 831547761248

**Result** ✓ Passed

CarCheck.co.uk page 4/12



 MOT #2
 2017-01-26 15:42

 MOT test number
 203675238482

Result × Failed

Fail

Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #1 2016-01-25 14:35
MOT test number 778738745774

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	23 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history		
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK SIE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-01-28
Last registration	2023-10-24
Complete history	See info



Registration #1	2013-01-28	27 mi
Registration #2	2016-01-25	27.325 mi
Registration #3	2017-01-26	33.559 mi
Registration #4	2017-01-27	33.558 mi
Registration #5	2017-10-31	35.251 mi
Registration #6	2018-10-29	38.216 mi
Registration #7	2019-10-29	41.854 mi
Registration #8	2019-10-29	41.866 mi
Registration #9	2020-07-16	44.688 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		D.777 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



## Dimensions & weight

Width	1789 mm
Height	1549 mm
Length	4133 mm
Wheel base	2595 mm
Kerb weight	1430 kg
Max. allowed weight	1940 kg

# Additional information

Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12

Number of axles2Engine numberA278J540