



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA S
Colour	Green
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-06
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-13
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	34
Total items failed	3

MOT #14 2023-01-05 10:42

MOT test number 405229015567

Result ✓ Passed

Next expiry date 2024-01-13

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm and deteriorated (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush 30-40% de-laminated (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material Both pipes before and after the flexi feeding the O/S/R (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive Front of engine (8.4.1 (a) (i))

MOT #13 2022-01-14 09:26

MOT test number 202547936507

Result ✓ Passed

- Advice** Slight leak from the oil pressure switch area
- Advice** Brake pipe corroded, covered in grease or other material Both rear slightly rusty (1.1.11 (c))
- Advice** Tyre slightly damaged/cracking or perishing Both front (5.2.3 (d) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view Small stone chips in the windscreen Zone A (3.2 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear arm rubber bush (5.3.4 (a) (i))

**MOT #12**

2021-09-07 16:12

MOT test number

524811809318

Result

✓ Passed

Minor

Windscreen damaged but not adversely affecting driver's view Small stone chips (3.2 (a) (i))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Slight oil leak from the oil pressure switch area

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

AdviceNearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear arm rubber bush (5.3.4 (a) (i))**Advice**

Tyre slightly damaged/cracking or perishing All tyres are perishing on the side walls (5.2.3 (d) (ii))

MOT #11

2020-09-07 08:49

MOT test number

287425053174

Result

✓ Passed

AdviceNearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
(5.3.4 (a) (i))**Advice**

Slight oil leak

Advice

Direction indicator slightly discoloured both rear (4.4.3 (a))

Advice

Both rear tyres perishing

MOT #10

2019-07-04 15:08

MOT test number

368918678462

Result

✓ Passed

AdviceNearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
(5.3.4 (a) (i))**Advice**

Small stone chips in windscreen

Advice

General under-body surface corrosion

**MOT #9** 2019-07-04 12:06**MOT test number** 830052845054**Result** ✗ Failed**Advice** Small stone chips in windscreen**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** General under-body surface corrosion**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #8** 2018-12-08 11:14**MOT test number** 731852333850**Result** ✓ Passed**MOT #7** 2018-12-08 11:14**MOT test number** 784215077425**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #6** 2017-11-25 10:29**MOT test number** 272931030964**Result** ✓ Passed**MOT #5** 2016-12-15 17:03**MOT test number** 737263012892**Result** ✓ Passed

**MOT #4** 2016-08-30 13:44**MOT test number** 399112327780**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #3** 2016-08-30 10:56**MOT test number** 454889965682**Result** ✗ Failed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #2** 2015-08-25 10:53**MOT test number** 297307648455**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2014-08-23 09:11**MOT test number** 909185234270**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✗
MOT
Expired:
13 January 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	13 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YD61TVO
Plate since	2019-06-29
Current registration	 YD61TVO
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-01
Last registration	2023-01-05
Complete history	See info



Registration #1	2011-09-01	13 mi
Registration #2	2014-08-23	18.538 mi
Registration #3	2015-08-25	25.020 mi
Registration #4	2016-08-30	31.976 mi
Registration #5	2016-08-30	31.976 mi
Registration #6	2016-12-15	33.599 mi
Registration #7	2017-11-25	39.876 mi
Registration #8	2018-12-08	46.854 mi
Registration #9	2019-01-01	50.000 mi
Registration #10	2019-01-01	50.000 mi
Registration #11	2019-01-01	50.000 mi
Registration #12	2019-01-01	50.000 mi
Registration #13	2019-01-01	50.000 mi
Registration #14	2019-01-01	50.000 mi
Registration #15	2019-01-01	50.000 mi
Registration #16	2019-01-01	50.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1331429