





report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT T200 LR P/V
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	175 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 3

Date 2021-12-10

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2021-09-04

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #13	2023-06-22 08:04
MOT test number	464114068198
Result	✓ Passed
Next expiry date	2024-06-21

MOT #12	2022-05-23 15:04
MOT test number	118507177614
Result	√ Passed

MOT #11	2021-08-05 08:00
MOT test number	295314029443
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #10		2020-06-09 12:08
MOT test	number	560798509050
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #9		2019-06-26 09:21
MOT test	number	326930566723
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Nail in tyre	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8		2018-07-05 13:42
MOT test	number	853480828725
Result		✓ Passed
Advice	Nearside Rear tyre outer sidewall is deterioated	
Advice	Offside Front anti roll bar drop link has slight play in it	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7	2017-07-04 09:13

MOT test number 838940685126

MOT #6 2016-06-14 09:06

MOT test number 519343259461

Result ✓ Passed

MOT #5 2016-06-14 09:06

MOT test number 551348152819

Result X Failed

Pass with rectification Offside Rear Stop lamp not working (1.2.1b)

MOT #4 2015-07-02 11:56

MOT test number 747873585183

Result \rightarrow Passed

MOT #3 2014-07-07 10:04

MOT test number 417568684177

Result ✓ Passed

MOT #2 2013-10-18 12:53

MOT test number 468441493265

Result X Failed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively

(8.2.2)

CarCheck.co.uk page 5/13



CP110MY report date: 2024-03-28

MOT #1 2013-10-18 12:53

MOT test number 467411493207

Result ✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/13



report date: 2024-03-28

21 June 2024

Tax & MOT check

MOT expiry date



Full MOT history

See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK JIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-07-07
Last registration	2023-06-22
Complete history	See info



Registration #1	2011-07-07	18 mi
Registration #2	2013-10-18	15.361 mi
Registration #3	2014-07-07	16.522 mi
Registration #4	2015-07-02	18.975 mi
Registration #5	2016-06-14	21.258 mi
Registration #6	2016-06-14	21.258 mi
Registration #7	2017-07-04	24.590 mi
Registration #8	2018-07-05	27.387 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	2044 mm
Height	598 mm
Length	4278 mm
Kerb weight	1392 kg
Max. allowed weight	2040 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	BD93214

CarCheck.co.uk page 13/13