



TOYOTA

ML56JLO

report date: 2024-03-28

General information

Make	TOYOTA
Model	AVENSIS VVTI COLOUR COLLECTION
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg



**MOT history**

MOT #21	2021-11-11 14:37
MOT test number	984169234514
Result	✓ Passed
Next expiry date	2022-11-10
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Advice	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

MOT #20	2020-10-27 12:38
MOT test number	705038592449
Result	✓ Passed

MOT #19	2020-10-27 09:53
MOT test number	809731805708
Result	✗ Failed
Fail	Rear Exhaust has a major leak of exhaust gases silencer joint (6.1.2 (a))

MOT #18	2019-10-24 15:32
MOT test number	781977924060
Result	✓ Passed

MOT #17	2018-10-24 09:26
MOT test number	275910436061
Result	✓ Passed

**MOT #16** 2018-10-23 09:45**MOT test number** 632747776043**Result** ✗ Failed**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #15** 2017-10-24 15:53**MOT test number** 826685521623**Result** ✓ Passed**Advice** Rear exhaust silencer mtg bracket weld is weak**MOT #14** 2017-10-24 11:07**MOT test number** 677883458626**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear exhaust silencer mtg bracket weld is weak**Advice** Nsf tyre uneven wear**MOT #13** 2016-11-01 17:02**MOT test number** 917151307095**Result** ✓ Passed**Advice** Nearside Front headlamp mainbeam image incorrect**Advice** Nearside Front Lower Ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #12**

2016-11-01 11:57

MOT test number

346269804583

Result**✗ Failed****Advice**

Nearside Front Lower Ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

Fail

Rear Brakes imbalanced across an axle (3.7.B.5b)

Fail

Offside Rear Braking system leaking frt to rear brake pipe corroded and leaking (3.6.A.1)

Advice

Nearside Front headlamp mainbeam image incorrect

MOT #11

2015-11-05 10:38

MOT test number

755490395564

Result**✓ Passed****Advice**

Engine covers and under trays fitted obscuring some components

Advice

Surface corrosion on some front suspension components

MOT #10

2015-11-05 10:38

MOT test number

386898954367

Result**✗ Failed****Advice**

Engine covers and under trays fitted obscuring some components

Advice

Surface corrosion on some front suspension components

Pass with rectification

Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #9

2014-10-16 10:36

MOT test number

485959784263

Result**✓ Passed****Notice**

Under-trays fitted obscuring some underside components

Notice

Some suspension componants corroded but structurally sound.

Notice

Engine covers fitted obscuring some components in the engine bay

**MOT #8** 2013-10-29 09:02**MOT test number** 409892403333**Result** ✓ Passed**MOT #7** 2013-10-29 09:02**MOT test number** 655992903369**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2012-11-01 11:22**MOT test number** 879076402359**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2011-11-08 08:59**MOT test number** 499252711435**Result** ✓ Passed**MOT #4** 2011-11-07 16:31**MOT test number** 257131211315**Result** ✗ Failed**Fail** Nearside Obligatory mirror missing (8.1.1)**Fail** Nearside Direction indicator missing (1.4.A.2b)

**MOT #3** 2010-10-15 10:43**MOT test number** 234528980210**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-10-15 10:43**MOT test number** 530018180213**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2009-10-05 12:31**MOT test number** 841188779269**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Cut in nearside front tyre outer side wall, no cords showing.



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-11-01
Last registration	2021-11-11
Complete history	See info



Registration #1	2006-11-01	24 mi
Registration #2	2009-10-05	37.317 mi
Registration #3	2010-10-15	50.657 mi
Registration #4	2011-11-07	57.430 mi
Registration #5	2011-11-08	57.340 mi
Registration #6	2012-11-01	63.188 mi
Registration #7	2013-10-29	67.899 mi
Registration #8	2014-10-16	73.838 mi
Registration #9	2015-11-05	81.122 mi
Registration #10	2015-11-05	81.122 mi
Registration #11	2016-11-05	81.122 mi
Registration #12	2017-11-05	81.122 mi
Registration #13	2018-11-05	81.122 mi
Registration #14	2019-11-05	81.122 mi
Registration #15	2020-11-05	81.122 mi
Registration #16	2021-11-05	81.122 mi
Registration #17	2022-11-05	81.122 mi
Registration #18	2023-11-05	81.122 mi
Registration #19	2024-11-05	81.122 mi
Registration #20	2025-11-05	81.122 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1480 mm
Length	4630 mm
Wheel base	2700 mm
Kerb weight	1245 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1ZZU685239