



PEUGEOT



WK57WEF


report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 S
Colour	Silver
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-16
Pictures	3
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-01-03
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	47
Total items failed	9

MOT #182023-01-04 17:14

MOT test number417263220311

Result✓ Passed

Next expiry date2024-01-03

- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement BOTH FRONT D-BUSHES. (5.3.4 (a) (i))
- Advice** Rear Coil spring corroded BOTH REARS (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge CLOSE TO LIMIT, INNER EDGE. (5.2.3 (e))
- Advice** Offside Front Oil leak, but not excessive DRIVESHAFT OIL SEAL. (8.4.1 (a) (i))
- Advice** Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced BOTH REAR AXLE BEAM MOUNTING AREAS. (5.3.3 (b) (i))

**MOT #17**

2022-12-29 14:31

**MOT test number**

394798595777

**Result****✗ Failed**

- Minor** Front Headlamp lens slightly defective BOTH FRONTS. (4.1.1 (b) (i))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Oil leak, but not excessive DRIVESHAFT OIL SEAL. (8.4.1 (a) (i))
- Advice** Rear Coil spring corroded BOTH FRONTS. (5.3.1 (b) (i))
- Minor** Offside Front Tyre obviously under inflated (5.2.3 (l))
- Fail** Offside Front Road wheel badly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge CLOSE TO LIMIT, INNER EDGE. (5.2.3 (e))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Suspension arm pin or bush likely to become detached REAR BUSH. (5.3.4 (a) (ii))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement BOTH FRONT D-BUSHES. (5.3.4 (a) (i))
- Advice** Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced BOTH REAR AXLE BEAM MOUNTING AREAS. (5.3.3 (b) (i))

**MOT #16**

2022-01-04 10:37

**MOT test number**

299428277383

**Result****✓ Passed****MOT #15**

2021-12-13 17:20

**MOT test number**

405923777653

**Result****✗ Failed**

- Advice** Tyre slightly damaged/cracking or perishing Nearside & Offside rear slightly cracking (5.2.3 (d) (ii))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #14**

2021-08-31 13:32

**MOT test number**

994143727992

**Result**

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))
- Advice** Nearside Suspension component pin or bush slightly worn Rear axle bush (5.3.4 (a) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Suspension component pin or bush slightly worn Rear axle bush (5.3.4 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #13**

2020-09-03 10:14

**MOT test number**

756384887039

**Result**

✓ Passed

- Advice** Offside Rear Light unit cracked
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2020-09-02 13:47

**MOT test number**

720322788410

**Result**

✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Light unit cracked
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2019-08-22 13:51

**MOT test number**

174546258129

**Result**

✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Both rear tyres on 3mm
- Advice** Offside Rear Light unit cracked
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #10**

2018-08-29 16:18

**MOT test number**

594686329215

**Result**

✓ Passed

**MOT #9** 2017-08-30 14:15**MOT test number** 858188939919**Result** ✓ Passed**MOT #8** 2016-08-11 13:04**MOT test number** 198579262283**Result** ✓ Passed**MOT #7** 2015-08-25 11:17**MOT test number** 635853862398**Result** ✓ Passed**MOT #6** 2014-08-14 14:33**MOT test number** 437296024289**Result** ✓ Passed**Notice** Rear brake discs slightly worn**Notice** Front brake discs worn**MOT #5** 2013-08-03 09:42**MOT test number** 609605013282**Result** ✓ Passed**Notice** Slight play in offside front steering arm**MOT #4** 2012-08-04 13:04**MOT test number** 827337212212**Result** ✓ Passed



MOT #3	2011-08-13 09:58
MOT test number	918105621238
Result	✓ Passed
<div>Notice</div> Near side inner steering joint has play	

MOT #2	2010-08-11 17:09
MOT test number	431513220229
Result	✓ Passed

MOT #1	2010-08-11 17:09
MOT test number	730043820209
Result	✗ Failed
<div>Pass with rectification</div> Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	





Tax & MOT check

X

Untaxed

Tax expired:  
28 January 2024

X

MOT

Expired:  
3 January 2024

Tax status	Expired at 28 January 2024
Days left	92 days too late
MOT expiry date	3 January 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-01
Last registration	2023-01-04
Complete history	<a href="#">See info</a>



Registration #1	2007-09-01	24 mi
Registration #2	2010-08-11	26.906 mi
Registration #3	2011-08-13	31.118 mi
Registration #4	2012-08-04	36.574 mi
Registration #5	2013-08-03	42.166 mi
Registration #6	2014-08-14	47.294 mi
Registration #7	2015-08-25	50.356 mi
Registration #8	2016-08-11	53.191 mi
Registration #9	2017-08-30	54.889 mi
Registration #10	2018-08-29	57.266 mi
Registration #11	2019-08-29	59.377 mi
Registration #12	2020-08-29	61.377 mi
Registration #13	2021-08-29	63.377 mi
Registration #14	2022-08-29	65.377 mi
Registration #15	2023-01-04	67.377 mi
Registration #16	2023-01-04	69.377 mi
Registration #17	2023-01-04	71.377 mi
Registration #18	2023-01-04	73.377 mi
Registration #19	2023-01-04	75.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1275 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FX6N3093351