



report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D2 SE LUX NAV
Colour	Red
Year of manufacture	2012
Top speed	115 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-07-05
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-15
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #10	2023-06-26 08:35
MOT test number	326830179313
Result	✓ Passed
Next expiry date	2024-07-15

MOT #9	2022-06-24 09:36
MOT test number	253887107829
Result	✓ Passed

MOT #8	2021-07-16 11:22
MOT test number	174213401034
Result	✓ Passed

MOT #7	2020-08-18 12:37
MOT test number	120684875821
Result	✓ Passed

MOT #6	2020-08-17 14:28
MOT test number	843374191501
Result	✗ Failed

MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MAJOR Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #5** 2019-08-16 08:03**MOT test number** 584268754241**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened LIPPED. (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened LIPPED. (1.1.14 (a) (ii))**MOT #4** 2018-08-20 13:46**MOT test number** 747439622134**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear tyres stepped on edges**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2017-06-14 13:27**MOT test number** 737221341570**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Tyre worn close to the legal limit and rear n/s and o/s (4.1.E.1)**MOT #2** 2016-06-08 15:29**MOT test number** 959303501056**Result** ✓ Passed**Advice** Nearside Rear child seat fitted**MOT #1** 2015-05-21 12:32**MOT test number** 728701345137**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
17 April 2024

✓

MOT

Expires:
15 July 2024

Tax status	Expired at 17 April 2024
Days left	12 days too late
MOT expiry date	15 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-06-16
Last registration	2023-06-26
Complete history	See info



Registration #1	2012-06-16	15 mi
Registration #2	2015-05-21	34.453 mi
Registration #3	2016-06-08	49.396 mi
Registration #4	2017-06-14	64.132 mi
Registration #5	2018-08-20	79.327 mi
Registration #6	2019-08-16	92.391 mi
Registration #7	2020-06-20	105.277 mi
Registration #8	2021-06-20	118.277 mi
Registration #9	2022-06-20	131.277 mi
Registration #10	2023-06-20	144.277 mi
Registration #11	2024-06-20	157.277 mi
Registration #12	2025-06-20	170.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1640 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4132480