



report date: 2024-03-28

General information

Make	FIAT
Model	PANDA DYNAMIC
Colour	Yellow
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	102 Nm at 2.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg





LABEL UNKNOWN



Internet history

Entry 2


Date	2021-06-14
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-06
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #16	2022-10-13 07:28
MOT test number	435862516129
Result	✓ Passed
Next expiry date	2023-10-19
Advice	Offside Front damage to bodywork, but no sharp edges
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside headlamp mountings damaged - requires attention

MOT #15	2022-10-13 07:28
MOT test number	551324667155
Result	✗ Failed
Advice	Offside Front damage to bodywork, but no sharp edges
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside headlamp mountings damaged - requires attention
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))

MOT #14	2021-10-06 12:55
MOT test number	716067849046
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Nail in tyre
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #13** 2021-10-06 07:20**MOT test number** 426365757274**Result** ✗ Failed**Advice** Nearside Front Nail in tyre**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #12** 2020-09-28 08:28**MOT test number** 189412397701**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #11** 2019-04-12 08:15**MOT test number** 120621883180**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #10** 2018-04-03 08:28**MOT test number** 476558219074**Result** ✓ Passed

- Advice** Direction indicators slightly discoloured all (1.4.A.2f)
- Advice** Offside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2017-04-20 08:09**MOT test number** 693628528522**Result** ✓ Passed

- Advice** Nearside Front tyre perished and split on inside shoulder.
- Advice** Offside Rear coil spring corroded (2.4.C.1b)

MOT #8 2017-04-06 08:23**MOT test number** 118755107704**Result** ✗ Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement rear bush (2.4.G.2)
- Advice** Offside Rear tyre perished in tread grooves
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Fail** Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement rear bush (2.4.G.2)
- Advice** Rear silencer outer skin very corroded.
- Advice** Nearside Front tyre worn low on inside edge & perished in tread grooves

**MOT #7** 2016-04-13 08:35**MOT test number** 589369060338**Result** ✓ Passed**Advice** Nearside Rear tyre 2.5mm tread depth**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Exhaust tail pipe in poor condition**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2015-04-13 09:18**MOT test number** 285183805480**Result** ✓ Passed**Notice** Rear exhaust box corroded**MOT #5** 2014-03-18 13:39**MOT test number** 175467474449**Result** ✓ Passed**Notice** Rear silencer rusty with slight blow**MOT #4** 2013-04-15 10:17**MOT test number** 785875503150**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)



MOT #3 2012-03-26 11:47

MOT test number 889266682005

Result ✓ Passed

Notice Rear exhaust box advanced corrosin

Advice Nearside Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #2 2011-04-06 10:33

MOT test number 619396591001

Result ✓ Passed

Advice Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #1 2010-04-15 11:00

MOT test number 824935900190

Result ✓ Passed

Advice Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-30
Last registration	2022-10-13
Complete history	See info



Registration #1	2006-09-30	26 mi
Registration #2	2010-04-15	16.355 mi
Registration #3	2011-04-06	19.265 mi
Registration #4	2012-03-26	22.353 mi
Registration #5	2013-04-15	24.085 mi
Registration #6	2014-03-18	25.928 mi
Registration #7	2015-04-13	28.665 mi
Registration #8	2016-04-13	30.821 mi
Registration #9	2017-04-06	32.497 mi
Registration #10	2017-04-20	32.529 mi
Registration #11	2018-04-06	35.377 mi
Registration #12	2019-04-06	35.377 mi
Registration #13	2020-04-06	35.377 mi
Registration #14	2021-04-06	35.377 mi
Registration #15	2022-04-06	35.377 mi
Registration #16	2023-04-06	35.377 mi
Registration #17	2024-04-06	35.377 mi
Registration #18	2025-04-06	35.377 mi
Registration #19	2026-04-06	35.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1589 mm
Height	1578 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	2105 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Engine number

3439193