



DW02HBW

report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | MINI           |
| Model               | MINI COOPER SD |
| Colour              | Blue           |
| Year of manufacture | 2013           |
| Top speed           | 130 mph        |
| 0 - 60 mph          | 8.7 seconds    |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 141 BHP             |
| Max. torque             | 305 Nm at 1.750 rpm |
| Engine capacity         | 1.995 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 53.3 mpg            |
| Consumption extra urban | 70.6 mpg            |
| Consumption combined    | 62.8 mpg            |
| CO2 emission            | 118 g/km            |
| CO2 label               | C                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-28                  |
| Pictures      | 10                          |
| Listing price | <a href="#">View report</a> |



source: yesauto.com



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-12-15 |
| MOT pass rate      | 91 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 1          |
| Total advice items | 5          |
| Total items failed | 1          |

|                  |   |
|------------------|---|
| MOT #11          | 2023-12-16 09:39  |
| MOT test number  | 142201137074  |
| Result           | ✓ Passed  |
| Next expiry date | 2024-12-15  |
| Advice           | COVERS UNDER BONNET UNDER CAR AND ON OUTER SILLS PREVENTING FULL INSPECTION |

|                 |  |
|-----------------|--|
| MOT #10         | 2022-09-26 11:11   |
| MOT test number | 593592059104   |
| Result          | ✓ Passed   |
| Minor           | Stop lamp(s) with a multiple light source up to 1/2 not functioning high level (4.3.1 (a) (i)) |
| Advice          | Nearside Front Tyre worn close to legal limit/worn on edge very low (5.2.3 (e))                |
| Advice          | Offside Front Tyre worn close to legal limit/worn on edge very low (5.2.3 (e))                 |

|                 |                  |
|-----------------|------------------|
| MOT #9          | 2021-09-24 10:56 |
| MOT test number | 226593072671     |
| Result          | ✓ Passed         |

|                 |   |
|-----------------|---|
| MOT #8          | 2021-09-23 15:42  |
| MOT test number | 302405461557  |
| Result          | ✗ Failed  |
| Fail            | Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b)) |



|               |                  |
|---------------|------------------|
| <b>MOT #7</b> | 2021-03-11 11:34 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 777251287116 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|

|               |                  |
|---------------|------------------|
| <b>MOT #6</b> | 2020-03-10 11:56 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 470975907688 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|

|               |                  |
|---------------|------------------|
| <b>MOT #5</b> | 2019-03-11 15:29 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 639444354134 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|

|               |                                  |
|---------------|----------------------------------|
| <b>Advice</b> | Offside Rear Alloy wheel buckled |
|---------------|----------------------------------|

|               |                  |
|---------------|------------------|
| <b>MOT #4</b> | 2018-03-23 14:35 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 907695745619 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|

|               |                  |
|---------------|------------------|
| <b>MOT #3</b> | 2017-11-16 15:31 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 393325338351 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|

|               |                  |
|---------------|------------------|
| <b>MOT #2</b> | 2016-10-10 14:15 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 480526245211 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|

|               |                  |
|---------------|------------------|
| <b>MOT #1</b> | 2016-05-21 12:50 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 930447958630 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
15 December 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 September         |
| <b>Days left</b>        | 125                             |
| <b>MOT expiry date</b>  | 15 December 2024                |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 49             |
| <b>Band</b>                                    | C              |
| <b>Single payment (12 months)</b>              | £ 35,00,-      |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | £ 36,75,-      |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

|          |  |
|----------|--|
| Damage 1 |  |
| Date     |  |
| Category |  |
| Type     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Type     |  |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MINI had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2019-09-29 |
| Current registration |            |
| Plate since          | 2019-09-29 |

More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 13                       |
| First mileage registration | 2013-03-27               |
| Last registration          | 2023-12-16               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2013-03-27 | 26 mi     |
| Registration #2  | 2016-05-21 | 26.405 mi |
| Registration #3  | 2016-10-10 | 27.915 mi |
| Registration #4  | 2017-11-16 | 39.166 mi |
| Registration #5  | 2018-03-23 | 39.176 mi |
| Registration #6  | 2019-03-11 | 45.711 mi |
| Registration #7  | 2020-03-10 | 54.346 mi |
| Registration #8  | 2020-03-27 | 55.277 mi |
| Registration #9  | 2020-03-27 | 55.277 mi |
| Registration #10 | 2020-03-27 | 55.277 mi |
| Registration #11 | 2020-03-27 | 55.277 mi |
| Registration #12 | 2020-03-27 | 55.277 mi |
| Registration #13 | 2020-03-27 | 55.277 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1683 mm |
| Height              | 1414 mm |
| Length              | 3729 mm |
| Wheel base          | 2467 mm |
| Kerb weight         | 1250 kg |
| Max. allowed weight | 1680 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 40 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 2                |

Number of seats 4

|                 |          |
|-----------------|----------|
| Number of axles | 2        |
| Engine number   | 71528575 |