



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	EXPERT L1 H1 HDI SWB P/V
Colour	Silver
Year of manufacture	2011
Top speed	90 mph
0 - 60 mph	17.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	39.2 mpg





Internet history

Entry 1

Date	2021-10-15
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-06
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	34
Total items failed	1

MOT #15 2023-10-07 12:47

MOT test number 966879448995

Result ✓ Passed

Next expiry date 2024-10-06

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14 2023-10-03 11:57

MOT test number 339419864373

Result ✗ Failed

- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm 1.0mm (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Headlamp aim unable to be tested not working (4.1.2 (b))
- Advice** Coolant leak low before test / front of engine
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))



MOT #13 2022-08-23 12:02

MOT test number 940151080598

Result ✔ Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Oil leak, but not excessive engine oil (8.4.1 (a) (i))

MOT #12 2021-06-23 09:46

MOT test number 937191023890

Result ✔ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11 2020-06-24 15:07

MOT test number 335994753602

Result ✔ Passed

Advice Coolant leak

Advice Oil leak, but not excessive (8.4.1 (a) (i))



MOT #10	2020-06-24 09:14
MOT test number	582135248042
Result	✗ Failed
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Coolant leak
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9	2019-05-24 17:50
MOT test number	334044436984
Result	✓ Passed

MOT #8	2019-05-20 08:56
MOT test number	754419461300
Result	✗ Failed
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a))
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #7	2018-08-06 16:21
MOT test number	252922747075
Result	✓ Passed



MOT #6	2018-07-30 13:17
MOT test number	930415409180
Result	✗ Failed
MAJOR	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
MAJOR	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
MAJOR	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
MAJOR	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #5	2017-07-25 08:28
MOT test number	502095566361
Result	✓ Passed
Advice	Nearside front brake pad warning wire broken
Advice	Ribbed belt noisy
Advice	Oil leak around sump

MOT #4	2016-07-18 14:02
MOT test number	209385800579
Result	✓ Passed

MOT #3	2015-07-27 11:17
MOT test number	806798405274
Result	✓ Passed

MOT #2	2015-07-27 11:17
MOT test number	546798805273
Result	✗ Failed
Pass with rectification	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)



MOT #1 2014-07-24 16:09

MOT test number 887085004204

Result ✓ Passed

Notice High level brake light inop



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
6 October 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	6 October 2024
Full MOT history	See MOT history



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	YX11UEY
Plate since	2024-03-28
Current registration	YX11UEY
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-07-31
Last registration	2023-10-07
Complete history	See info



Registration #1	2011-07-31	15 mi
Registration #2	2014-07-24	34.674 mi
Registration #3	2015-07-27	46.052 mi
Registration #4	2016-07-18	53.258 mi
Registration #5	2017-07-25	60.554 mi
Registration #6	2018-07-30	66.600 mi
Registration #7	2018-08-06	66.630 mi
Registration #8	2019-05-20	69.069 mi
Registration #9	2019-05-20	69.069 mi
Registration #10	2019-05-20	69.069 mi
Registration #11	2019-05-20	69.069 mi
Registration #12	2019-05-20	69.069 mi
Registration #13	2019-05-20	69.069 mi
Registration #14	2019-05-20	69.069 mi
Registration #15	2019-05-20	69.069 mi
Registration #16	2019-05-20	69.069 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2194 mm
Height	1980 mm
Length	4805 mm
Kerb weight	1673 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	JBBY0061993