





report date: 2024-03-29

General information

Make	FORD
Model	MONDEO GHIA 16V
Colour	Silver
Year of manufacture	2004
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	38.7 mpg
Consumption combined	30.1 mpg
CO2 emission	218 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-29


Internet history

Entry 2

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2021-01-21
Pictures	71

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT h	nistory
-------	---------

MOT expiry date	2025-01-23
MOT pass rate	89 %
MOT passed	17
Failed MOT tests	2
Total advice items	9
Total items failed	6

MOT #19	2024-01-19 15:43
MOT test number	453548548796
Result	✓ Passed
Next expiry date	2025-01-23
Advice Brake pad(s) wearing thin Borderline (1.1.13 (a) (ii))	

MOT #18	2023-01-24 15:43
MOT test number	685347323225
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #17	2022-01-07 09:44
MOT test number	302278105170
Result	✓ Passed

MOT #16	2021-01-20 09:45
MOT test number	406690962521
Result	√ Passed

MOT #15	2019-10-28 12:09
MOT test number	891922727548
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #14 2018-10-15 12:45

MOT test number 964964508955

MOT #13 2017-10-11 11:30

MOT test number 875975387421

Result
✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12 2017-10-11 09:40

MOT test number 399513428114

Result X Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Exhaust emits dense blue smoke at idle (7.3.A.2b)

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #11 2016-10-11 08:58

MOT test number 865691584187

Result
✓ Passed

MOT #10 2015-10-14 15:16

MOT test number 684377785713

Advice Nearside Front Anti-roll bar linkage damaged but not seriously weakened (2.4.G.1)

Advice Offside Front Anti-roll bar linkage damaged but not seriously weakened (2.4.G.1)

CarCheck.co.uk page 4/13



MOT #9

EA54CNN

report date: 2024-03-29

2014-10-08 13:41

MOT test number 535071384288

Result ✓ Passed

MOT #8 2013-10-14 12:21

MOT test number 368627183462

Result ✓ Passed

MOT #7 2012-10-16 16:14

MOT test number 968690292263

Result \(\sqrt{Passed} \)

MOT #6 2011-10-27 11:52

MOT test number 328540801339

MOT #5 2011-10-27 11:52

MOT test number 297520201305

Result × Failed

Pass with rectification Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Pass with rectification Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #4 2010-11-01 11:15

MOT test number 901155700327

Result / Passed

Advice Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)

Notice BOTH REAR INDICATORS FADED

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3	2009-10-19 17:10
MOT test number	253212499254
Result	✓ Passed
MOT #2	2008-10-23 11:25
MOT test number	942907198232
Result	✓ Passed
MOT #1	2007-10-22 12:31
MOT test number	930795297234
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-10-31
Last registration	2024-01-19
Complete history	See info



Registration #1	2004-10-31	23 mi
Registration #2	2007-10-22	12.023 mi
Registration #3	2008-10-23	15.601 mi
Registration #4	2009-10-19	18.629 mi
Registration #5	2010-11-01	21.744 mi
Registration #6	2011-10-27	25.346 mi
Registration #7	2012-10-16	27.075 mi
Registration #8	2013-10-14	28.211 mi
Registration #9	2014-10-08	29.540 mi
Registration #10	2015-10-14	30.182 mi
Registration #11	2016-10-11	30.741 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11,177 mi

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1931 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1432 kg
Max. allowed weight	3540 kg

Additional information

Fuel tank capacity	58
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number 4K08037