



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	MR2 ROADSTER
Colour	Silver
Year of manufacture	2004
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	178 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-09-16
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-01
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	39
Total items failed	10

MOT #242023-11-21 09:27

MOT test number449727797011

Result✓ Passed

Next expiry date2024-12-01

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases At the flexi section (6.1.2 (a))
- Advice** Coil spring corroded Both rear coil springs corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Coil spring corroded Both front coil springs corroded (5.3.1 (b) (i))
- Advice** Front headlamps slightly misted
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #23**

2022-11-21 11:20

MOT test number

408117749816

Result

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases Exhaust flexi section (6.1.2 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #22

2021-12-02 09:10

MOT test number

826546826281

Result

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #21

2021-02-25 14:41

MOT test number

998924997400

Result

✓ Passed

**MOT #20** 2021-02-23 10:06**MOT test number** 944783495203**Result** ✗ Failed**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Offside Rear Brake lever has restricted free movement handbrake lever (1.1.15 (e))**MOT #19** 2020-02-20 11:13**MOT test number** 942226859971**Result** ✓ Passed**MOT #18** 2019-03-02 12:52**MOT test number** 274141943755**Result** ✓ Passed**Advice** Offside Front Coil spring worn (5.3.1 (b) (i))**MOT #17** 2019-03-02 10:34**MOT test number** 619063329571**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Offside Front Coil spring worn (5.3.1 (b) (i))**MOT #16** 2017-10-28 10:12**MOT test number** 692037830718**Result** ✓ Passed

**MOT #15** 2016-11-28 14:21**MOT test number** 601072404882**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 3.0 mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 2.5 mm (4.1.E.1)**MOT #14** 2016-11-28 09:30**MOT test number** 422529421526**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Advice** Nearside Front Tyre worn close to the legal limit 2.5 mm (4.1.E.1)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Advice** Engine management light illuminated**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Offside Front Tyre worn close to the legal limit 3.0 mm (4.1.E.1)**MOT #13** 2015-11-28 10:50**MOT test number** 324161714052**Result** ✓ Passed**Advice** Engine management light on**Advice** Nearside rear brake slight bind**Advice** Nearside headlamp damaged

**MOT #12** 2015-11-28 10:50**MOT test number** 434891897067**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside headlamp damaged**Advice** Engine management light on**Advice** Nearside rear brake slight bind**MOT #11** 2014-11-29 10:26**MOT test number** 588573034313**Result** ✓ Passed**Notice** Engine Management Light on**MOT #10** 2013-11-30 12:21**MOT test number** 208254933327**Result** ✓ Passed**MOT #9** 2013-11-30 10:15**MOT test number** 487044633423**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #8** 2012-11-17 10:36**MOT test number** 898972622308**Result** ✓ Passed**MOT #7** 2011-11-05 10:22**MOT test number** 776039301336**Result** ✓ Passed

**MOT #6** 2010-11-13 09:57**MOT test number** 464027610406**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2010-11-13 09:57**MOT test number** 484107710329**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2009-11-21 13:16**MOT test number** 661855629376**Result** ✓ Passed**MOT #3** 2008-11-24 15:33**MOT test number** 191629528386**Result** ✓ Passed**MOT #2** 2008-03-29 08:44**MOT test number** 423259088007**Result** ✓ Passed**MOT #1** 2007-04-17 16:52**MOT test number** 393387007152**Result** ✓ Passed**Notice** Surface corrosion to front discs**Notice** Front tyres wearing inner edge



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
1 December 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	1 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	FX54ZVE
Plate since	2024-03-29
Current registration	FX54ZVE
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-09-02
Last registration	2023-11-21
Complete history	See info



Registration #1	2004-09-02	23 mi
Registration #2	2007-04-17	36.325 mi
Registration #3	2008-03-29	42.763 mi
Registration #4	2008-11-24	45.903 mi
Registration #5	2009-11-21	52.620 mi
Registration #6	2010-11-13	58.626 mi
Registration #7	2011-11-05	62.706 mi
Registration #8	2012-11-17	64.805 mi
Registration #9	2013-11-30	66.697 mi
Registration #10	2013-11-30	66.697 mi
Registration #11	2014-11-29	71.315 mi
Registration #12	2015-11-28	75.066 mi
Registration #13	2015-11-28	75.066 mi
Registration #14	2016-11-27	75.066 mi
Registration #15	2016-11-27	75.066 mi
Registration #16	2016-11-27	75.066 mi
Registration #17	2016-11-27	75.066 mi
Registration #18	2016-11-27	75.066 mi
Registration #19	2016-11-27	75.066 mi
Registration #20	2016-11-27	75.066 mi
Registration #21	2016-11-27	75.066 mi
Registration #22	2016-11-27	75.066 mi
Registration #23	2016-11-27	75.066 mi
Registration #24	2016-11-27	75.066 mi
Registration #25	2016-11-27	75.066 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1695 mm
Height	1240 mm
Length	3885 mm
Wheel base	2450 mm
Kerb weight	960 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	1ZZ1660206