



report date: 2024-03-28

General information

| | |
|---------------------|---------------------------------|
| Make | CITROEN |
| Model | BERLINGO E-HDI AIRDREAM XTR EGS |
| Colour | Brown |
| Year of manufacture | 2012 |
| Top speed | 103 mph |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 91 BHP |
| Max. torque | 230 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 55.4 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 58.9 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-29 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-12-22 |
| MOT pass rate | 67 % |
| MOT passed | 8 |
| Failed MOT tests | 4 |
| Total advice items | 9 |
| Total items failed | 9 |

MOT #12 2022-12-12 16:36

MOT test number 473515692929

Result ✓ Passed

Next expiry date 2023-12-22

Advice No rear seats fitted time of test

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11 2022-12-12 10:40

MOT test number 627756606049

Result ✗ Failed

Advice No rear seats fitted time of test

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Horn not working (7.7 (a))

Fail Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

MOT #10 2021-12-20 15:38

MOT test number 474558607813

Result ✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2021-12-20 10:02**MOT test number** 582504439107**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Horn not working (7.7 (a))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Windscreen washer not working (3.5 (a))**MOT #8** 2020-12-23 12:12**MOT test number** 545883309041**Result** ✓ Passed**MOT #7** 2020-12-14 17:48**MOT test number** 817389016605**Result** ✗ Failed**Fail** Offside Front Brake hose excessively chafed been rubbing on liner for wheelarch (1.1.12 (b) (ii))**MOT #6** 2019-10-25 10:38**MOT test number** 471251236184**Result** ✓ Passed**Minor** Offside Front Brake hose slightly chafed (1.1.12 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2018-06-07 09:48**MOT test number** 881072428071**Result** ✓ Passed**Advice** All tires worn



| | |
|-------------------------|--------------------------------------|
| MOT #4 | 2017-05-30 09:16 |
| MOT test number | 421749350872 |
| Result | ✓ Passed |
| MOT #3 | 2016-04-26 13:17 |
| MOT test number | 211672234761 |
| Result | ✓ Passed |
| MOT #2 | 2015-05-22 09:37 |
| MOT test number | 686622045106 |
| Result | ✓ Passed |
| MOT #1 | 2015-05-22 09:37 |
| MOT test number | 758812545131 |
| Result | ✗ Failed |
| Pass with rectification | Offside Headlamp aim too high (1.8) |
| Pass with rectification | Nearside Headlamp aim too high (1.8) |



Tax & MOT check

X

Untaxed

Tax expired:
13 June 2023

X

MOT

Expired:
22 December 2023

| | |
|------------------|---------------------------------|
| Tax status | Expired at 13 June 2023 |
| Days left | 320 days too late |
| MOT expiry date | 22 December 2023 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|-----------------------------------------|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 0 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2012-05-21 |
| Last registration | 2022-12-12 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-05-21 | 26 mi |
| Registration #2 | 2015-05-22 | 19.329 mi |
| Registration #3 | 2016-04-26 | 32.103 mi |
| Registration #4 | 2017-05-30 | 45.046 mi |
| Registration #5 | 2018-06-07 | 52.968 mi |
| Registration #6 | 2019-10-25 | 56.279 mi |
| Registration #7 | 2020-12-14 | 57.763 mi |
| Registration #8 | 2021-05-20 | 58.277 mi |
| Registration #9 | 2021-05-20 | 58.277 mi |
| Registration #10 | 2021-05-20 | 58.277 mi |
| Registration #11 | 2021-05-20 | 58.277 mi |
| Registration #12 | 2021-05-20 | 58.277 mi |
| Registration #13 | 2022-12-12 | 58.277 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 83% |
| Children | 74% |
| Pedestrian | 33% |
| Safety systems | 40% |
| Overall rating | 67% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1862 mm |
| Length | 4380 mm |
| Wheel base | 2728 mm |
| Kerb weight | 1430 kg |
| Max. allowed weight | 2070 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | JBDX3004675 |